

R2-B24

FROM: R.J. McCORMAC III
DATE: FEBRUARY 23, 1993
SUBJECT: CONTAMINATED DIRT REMOVAL FROM WEST END OF PLANT
TO: R. FISCHER
E. REITLER

G. Lowder is preparing to remove whatever contaminated dirt necessary from the area immediately outside the west wall of the plant. We need to furnish the following information:

1. Clothing required by personnel doing the digging. Note, all excavation will be done by shovel. R. Fischer
2. Exact location (boundaries) of the dig. R. Fischer
3. Identification of layer of soil to be removed; i.e. can the top 2 or 3 feet be removed first, as clean, then the contaminated soil for burial. R. Fischer/J. McCormac
4. What samples are to be pulled to assure all necessary soil has been removed? How many samples? What analysis? R. Fischer
5. Method of disposal. Where? How? What container? J. McCormac

Roger is out the week of 2/22 and Jim is out week of 3/1. There is no required completion date. The above questions should be answered and a schedule prepared by week ending 3/12.


R.J. McCORMAC III

C-15