

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Subhash C. Sabharwal, M.D. Cardiovascular Diseases 17000 Hubbard Drive Suite 200 Dearborn, MI 48126		2. NRC/REGIONAL OFFICE <p style="text-align: center;">UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 2443 WARRENVILLE ROAD, SUITE 210 LISLE, IL 60532-4352</p>	
REPORT 2006-001			
3. DOCKET NUMBER(S) <p style="text-align: center;">030-37001</p>	4. LICENSEE NUMBER(S) <p style="text-align: center;">21-32588-01</p>	5. DATE(S) OF INSPECTION <p style="text-align: center;">June 14, 2006</p>	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.


 _____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

 (Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Robert P. Hays		6/14/2006

(10-2003)
10 CFR 2.201**Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Subhash C. Sabharwal, M.D.		2. NRC/REGIONAL OFFICE Region III	
REPORT NUMBER(S) 2006-001			
3. DOCKET NUMBER(S) 03037001	4. LICENSE NUMBER(S) 21-32588-01	5. DATE(S) OF INSPECTION June 14, 2006	
6. INSPECTION PROCEDURES USED 87130 (10/24/02)		7. INSPECTION FOCUS AREAS 03.01- 03.07	
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTACT Denise Smith, Office Mgr.	4. TELEPHONE NUMBER 313/271-2580
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: June 2011	
<input type="checkbox"/> Field Office			
<input type="checkbox"/> Temporary Job Site			

PROGRAM SCOPE

The licensee was a private practice clinic authorized by the license to use any byproduct material permitted by 10 CFR 35.100, as needed for any uptake, dilution and excretion study permitted by 10 CFR 35.100, and 10 CFR 35.200, as needed (excluding xenon-133) for any imaging and localization study permitted by 10 CFR 35.200, at the location specified on the license. Licensed activities were conducted 2 days per week in the nuclear medicine suite. The nuclear medicine department was staffed with 2 part-time alternating nuclear medicine technologists (NMT) who routinely conducted 2-4 patient procedures on Wednesdays and Saturdays each week. The licensee received unit doses as ordered from a local nuclear pharmacy for cardiac rest and stress studies. All waste was held for decay-in-storage (DIS) or returned to the nuclear pharmacy as a limited quantity shipment.

Performance Observations

During the inspection, the licensee's NMT demonstrated/discussed: (1) package check-in procedures and wipe test counting; (2) dosimetry; (3) dose calibrator checks; (4) unit dose handling procedures; (5) security of licensed material; (6) radiation safety program audits; and (7) rad waste procedures.

7588