



**Docket File Information**  
**SAFETY INSPECTION REPORT**  
**AND COMPLIANCE INSPECTION**

1. LICENSEE <b>The Medical Physics Group LTD</b> REPORT NUMBER(S) <b>2006-001</b>		2. NRC/REGIONAL OFFICE <b>Region III</b> <b>2443 Warrenville Road</b> <b>Lisle, IL 60532</b>	
3. DOCKET NUMBER(S) <b>030-18575</b>	4. LICENSE NUMBER(S) <b>24-24392-013</b>	5. DATE(S) OF INSPECTION <b>July 14, 2006</b>	
6. INSPECTION PROCEDURES USED <b>87126</b>		7. INSPECTION FOCUS AREAS <b>03.01, 03.02, 03.03, 03.04, 03.05, 03.06, and 03.07</b>	

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM <b>03225</b>	2. PRIORITY <b>E 5</b>	3. LICENSEE CONTACT <b>Robert Turco, Ph.D, RSO</b>	4. TELEPHONE NUMBER <b>314.251.7258</b>
----------------------------	---------------------------	---	--

Main Office Inspection      Next Inspection Date: July 2011

Field Office    615 New Ballas Rd, St. Louis, MO (St. John's Mercy Med. Ctr.)

Temporary Job Site    \_\_\_\_\_

**PROGRAM SCOPE**

This private medical physics consulting company employed 4 medical physicists who provided various health physics services to licensees in the St. Louis area. Licensed activities included leak testing of sealed sources and dose calibrator QA tests. The licensee possessed 4 sources that it used for dose calibrator tests. The company performed survey instrument calibration services utilizing a Cs-137 calibrator unit under NRC license no. 24-00794-03 issued to St. John's Mercy Medical Center.

This inspection consisted of a tour of the calibration lab and radioactive material storage areas; review of selected records; interviews with licensee staff, and independent area surveys.