

September 24, 1992

To: Dr. R. Fuhrmeister  
Senior Allegation Coordinator  
Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406-1415

7C [ From: ]

Thank you for your response on May 8, 1992 (your Docket No. 030-00883) and the inspection report. My complaint in February was based on observed disregard of safe operating procedures for iodinations by [redacted] Rm. A-319, Nelson Labs., Busch Campus -- a lab. which I am obliged to share. What worries me particularly is general disregard for rules, procedures and expected conduct. Since February I have extensively interacted with R.E.H.S. and University administrators in an attempt to remove or at least minimise the risk to my and others health and safety. I have made little progress.

You are no doubt aware that on September 17, 1992, a high count ring badge belonging to [redacted] was reported. I am obviously very concerned where and how this contamination occurred. I hope there will be a thorough investigation of the iodination program and the associated record keeping at Rutgers, particularly for the case of [redacted].

If I can be of any help, please contact me.

Thank you.

B/1