


Betty Garrett - Fw: New Kerosene Seep - West Wall

From: "Oscar Paulson" <paulson@tribcsp.com>
To: "Stephen Cohen" <SJC7@nrc.gov>
Date: 07/17/2006 11:16 AM
Subject: Fw: New Kerosene Seep - West Wall
CC: <shelley@tribcsp.com>

Stephen Cohen:

Below is an image of a new kerosene seep on the West wall around TWM-90 the perched monitor well from which substantial organics were recovered. Clearly this seep was feeding the well. The remains of the monitor well (basal section of slotted pipe) are on the right hand side of the image. The seep extends from the leftmost red pin flag to the rightmost red pin flag (behind monitor well TMW-90) with a length of approximately thirty-four (34) feet. On the left side of the seep a pocket cellular telephone has been inserted for scale.



All of the darkened sandstone contains some level of kerosene. The darker the staining the higher the kerosene concentration.

Oscar Paulson
Facility Supervisor

Mail Envelope Properties (44BBA9C6.A72 : 19 : 43634)

Subject: Fw: New Kerosene Seep - West Wall
Creation Date 07/17/2006 11:17:33 AM
From: "Oscar Paulson" <paulson@tribcsp.com>
Created By: paulson@tribcsp.com

Recipients

nrc.gov
OWGWPO03.HQGWDO01
SJC7 (Stephen Cohen)

tribcsp.com
shelley CC

Post Office
OWGWPO03.HQGWDO01

Route
nrc.gov
tribcsp.com

Files	Size	Date & Time
MESSAGE	733	07/17/2006 11:17:33 AM
TEXT.htm	1876	
West-Wall_seep.png	340122	
Mime.822	470361	

Options

Expiration Date: None
Priority: Standard
ReplyRequested: No
Return Notification: None

Concealed Subject: No
Security: Standard