

Dominion Nuclear Connecticut, Inc.  
Millstone Power Station  
Rope Ferry Road  
Waterford, CT 06385



**Dominion™**

**JUL 7 2006**

U.S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555

Serial No. 06-546  
MPS Lic/WDB R0  
Docket No. 50-423  
License No. NPF-49

**DOMINION NUCLEAR CONNECTICUT, INC.**  
**MILLSTONE POWER STATION UNIT 3**  
**CANCELLATION OF LICENSEE EVENT REPORT 2004-003-00**

On January 3, 2005, Dominion Nuclear Connecticut, Inc., (DNC) submitted Licensee Event Report (LER) MP3-2004-003 pursuant to 10 CFR 50.73(a)(2)(i)(B) and 10 CFR 50.73(a)(2)(v)(B). This LER documented two conditions at Millstone Power Station Unit 3 (MPS 3), in which the High Pressure Safety Injection (HPSI) system, a component of the Emergency Core Cooling system (ECCS) subsystem listed in MPS 3 Technical Specification 3.5.2, previously evaluated as operable, may have been inoperable. Subsequent to the submittal of the LER, a technical evaluation was completed that concluded that while the HPSI system was degraded, the ECCS subsystem remained operable in the as found condition. Therefore, DNC is formally withdrawing LER MP3-2004-003.

If you have any questions or require additional information, please contact Mr. David W. Dodson at (860) 447-1791, extension 2346.

Very truly yours,

  
J. Alan Price  
Site Vice President - Millstone

JE22

Attachments: None

Commitments made in this letter: None.

cc: U.S. Nuclear Regulatory Commission  
Region I Regional Administrator  
475 Allendale Road  
King of Prussia, PA 19406-1415

Mr. V. Nerses  
NRC Senior Project Manager Millstone Units 2 and 3  
U.S. Nuclear Regulatory Commission, Mail Stop 8 C2  
One White Flint North  
11555 Rockville Pike  
Rockville, MD 20852-2738

Mr. S. M. Schneider  
NRC Senior Resident Inspector  
Millstone Power Station