NRC FORM 591M PART 1 (10-2003)		U.S. NUCLEAR REGULATORY COMMIS
10 CFR 2.201 SAFETY	INSPECTION REPORT AND CO	MPLIANCE INSPECTION
1. LICENSEE/LOCATION INSPECTED: McElroy Coal Company 1800 Washington Road Pittsburgh, PA 15241	U.S. I Regio	EGIONAL OFFICE Nuclear Regulatory Commission on I, 475 Allendale Road
REPORT 2006-001	King	of Prussia, Pennsylvania 19406-1415
3. DOCKET NUMBER(S) 030-35721	4. LICENSE NUMBER(S) 37-25561-01	5. DATE(S) OF INSPECTION July 13, 2006
LICENSEE:		· ·
Nuclear Regulatory Commission (NRC) rule of procedures and representative records, it Image: State of the inspection findin 2. Previous violation(s) closed. 3. The violation(s), specifically de identified, non-repetitive, and corr	es and regulations and the conditions of yo interviews with personnel, and observations gs, no violations were identified. escribed to you by the inspector as non-cite ective action was or is being taken, and the	they relate to radiation safety and to compliance with the bur license. The inspection consisted of selective examinat s by the inspector. The inspection findings are as follows: ed violations, are not being cited because they were self- e remaining criteria in the NRC Enforcement Policy,
NUREG-1600, to exercise discret	ion, were satisfied. s/were discussed involving the following re	equirement(s) and Corrective Action(s):
	• • •	
		r attached, were in violation of NRC requirements and are
being cited. This form is a NOTIC	E OF VIOLATION, which may be subject to	o posting in accordance with 10 CFR 19.11.
•		
hereby state that, within 30 days, the action	ith the requirements of 10 CFR 2.201 (corr	e taken to correct the violations identified. This statement o ective steps already taken, corrective steps which will be ta
date when full compliance will be achieved) Title	. I understand that no further written respon Printed Name	nse to NRC will be required, unless specifically requested. Signature Date
LICENSEE'S REPRESENTATIVE ·		
•		1 J 1

.

ý.