

From: "Zabel, Joe" <JZabel@atlintl.com>
To: <jad@nrc.gov>
Date: 07/07/2006 10:49:09 AM
Subject: Comments on Pilgrim AMP document

Hi Jim:

In going over and incorporating your comments on the Pilgrim AMP document, I discovered that your comment change to page 65, lines 18-19, was missing a portion. The following is the excerpt from your comment that reflects the exclusion (...):

From an additional historical perspective, the SSW system at PNPS has experienced leaks on the buried inlet (screenhouse to auxiliary bays) piping as a result of internal corrosion. The original piping material was rubber-lined carbon steel wrapped with ... occurred in 1995 and 1997. In addition, the SSW buried discharge piping (also rubber-lined carbon steel with external pipe wrapping, same as inlet piping) from the auxiliary bays to the discharge canal also experienced severe internal corrosion due to failure of the rubber lining. Two 40-foot lengths of 22-inch diameter pipes (one on each loop) were replaced in 1999 as a result of the failed rubber lining and internal corrosion. These spools were replaced with carbon steel coated internally and externally with an epoxy coating. The piping that was removed was examined after its wrapping was removed and its external surface was found to be in good condition. Since that time, the entire length of both SSW buried discharge loops have been lined internally with cured-in-place pipe linings-"B" Loop in 2001 and "A" Loop in 2003.

Please look this over and send me the missing words to complete your comment.

Thanks,

Joe

Joe Zabel

Senior Writer/Outreach Manager

Advanced Technologies & Laboratories International, Inc.

20010 Century Boulevard, Suite 500

Germantown, MD 20874

Tel: (301) 515-6783

Fax: (301) 972-6904

CC: "Orr, Mark" <MPOrr@atlintl.com>

Mail Envelope Properties (44AE745D.2BE : 2 : 53950)

Subject: Comments on Pilgrim AMP document
Creation Date 07/07/2006 10:48:46 AM
From: "Zabel, Joe" <JZabel@atlintl.com>

Created By: JZabel@atlintl.com

Recipients

nrc.gov
 OWGWPO03.HQGWDO01
 JAD (James Davis)

atlintl.com
 MPOrr CC (Mark Orr)

Post Office

OWGWPO03.HQGWDO01

Route

nrc.gov
 atlintl.com

Files	Size	Date & Time
MESSAGE	1677	07/07/2006 10:48:46 AM
TEXT.htm	5230	
Mime.822	8769	

Options

Expiration Date: None
Priority: Standard
ReplyRequested: No
Return Notification: None

Concealed Subject: No
Security: Standard

Junk Mail Handling Evaluation Results

Message is eligible for Junk Mail handling
 This message was not classified as Junk Mail

Junk Mail settings when this message was delivered

Junk Mail handling disabled by User
 Junk Mail handling disabled by Administrator
 Junk List is not enabled
 Junk Mail using personal address books is not enabled
 Block List is not enabled