Dominion Nuclear Connecticut, Inc. Millstone Power Station Rope Ferry Road Waterford, CT 06385



AUG - 8 2006

U.S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, DC 20555 Serial No. 06-669 NSS&L/DF R0 Docket No. 50-336 License No. DPR-65

DOMINION NUCLEAR CONNECTICUT, INC. MILLSTONE POWER STATION UNIT 2 SPECIAL REPORT FOR INOPERABLE RADIATION MONITOR

In accordance with the reporting requirements of the Millstone Power Station Unit 2 (MPS2) Technical Specifications (TS), Section 3.3.3.1, Table 3.3-6, Action 17, Dominion Nuclear Connecticut, Inc. (DNC) hereby submits a Special Report for the number of operable radiation monitoring channels less than required by TS 3.3.3.1, Table 3.3-6, Action 17, Step 2 states, "Prepare and submit a Special Report to the Commission pursuant to Specification 6.9.2 within 14 days following discovery outlining the action taken, the cause of the inoperability and the plans and schedule for restoring the system to operable status."

On July 21, the noble gas effluent radiation monitor for the MPS2 stack, monitor RM-8168, was returned to operable status after installation of hardware upgrades and subsequent post modification testing and restoration activities.⁽¹⁾

On July 25, 2006, RM-8168 was removed from service due to intermittent detector failure. At that time, one channel was declared inoperable and action under TS 3.3.3.1 was taken. Troubleshooting and repair of the component was completed on August 4, 2006. Currently the system is being monitored to ensure the corrective actions were effective. Restoration of the system to an operable status is currently scheduled for August 11, 2006. During this period, compensatory measures in accordance with station procedures are in place. The actions associated with the repair of RM-8168 are being tracked by DNC's corrective action program.

If you have any questions or require additional information, please contact Mr. David W. Dodson at (860) 447-1791, extension 2346.

Very truly yours,

Price

⁽¹⁾ DNC letter, "Dominion Nuclear Connecticut Inc, Millstone Power Station Unit 2, Special Report for Radiation Monitor," dated July 20, 2006



Serial No. 06-669 Special Report for Inoperable Radiation Monitor Page 2 of 2

Site Vice President - Millstone

Attachments: None

10.00

Commitments made in this letter: None.

cc: U.S. Nuclear Regulatory Commission Region I Regional Administrator 475 Allendale Road King of Prussia, PA 19406-1415

> Mr. V. Nerses NRC Senior Project Manager Millstone Units 2 and 3 U.S. Nuclear Regulatory Commission, Mail Stop 8 C2 One White Flint North 11555 Rockville Pike Rockville, MD 20852-2738

Mr. S. M. Schneider NRC Senior Resident Inspector Millstone Power Station