



MIR 1 4 2006

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D.C. 20555 CC: U.S. Nuclear Regulatory Commission Region 1 Attn: Regional Administrator 475 Allendale Road King of Prussia, PA 19406

Docket Nos. 03021004, 03017073

License Nos. 06-19165-02G, 06-19165-01

Reply to a Notice of Violation: Inspection 03021004 and 03017073/2006001

1. The reason for the violation; under that period of reporting, was due to assigned responsibilities and a manual clerical system.

The assigned secretary under the guidance of the RSO, was responsible for manually coping invoices of customers who purchased new Isotopes and then reporting during that cited time period, the appropriate paperwork was not submitted during allotted mailing time.

2. The following corrective actions have taken place, an internal Fischer Technology, Inc. (CAR) Corrective Action Report was issued, and a new data base program was produced to provide this information without any manual researching or coping of invoices.

Second the quarterly report has become part of our automatic computer ISO 9001 reporting system. A reminder will be automatically generated to the responsible party for collecting and sending out the data. This reminder will continuously be generated until the requested is fulfilled. This will become part of the Quality Department procedures under the direction of the RSO.

- 3. As described in number 2 the following will be implemented.
- 4. All procedures will be in place as of August 25, 2006 to comply fully to all reporting requirements as listed 10 CFR 31.5

Sincerely Submitted,

Michael Haller
Technical Director

cc: Ray Moncevicius Radiation Safety Officer

IE07