

G 4040 South Linden Road Flint, Michigan 48507 810 733.0790 Tel 810.733.0235 Fax

Abdul K. Alawwa, M.D., F.A.C.C. ♥ Wayne J. Breece, M.D. ♥ David A. Brill, M.D., F.A.C.C. ♥ Jeffrey L. Harris, D.O., F.A.C.C. Nicole Bice, P.A.C. ♥ Shelley Littleton, P.A.C. ♥ Michelle Prunkard, P.A.C. August 21, 2006

United States Nuclear Regulatory Commission Region III, Materials Licensing Section 2443 Warrenville Road, Ste 210 Lisle, IL 60532-4352

Ammendment to license # 21-32624-01. Re:

Cardiology Consultants of East Michigan

Dear Sir/Madam:

We would like to amend our current NRC license to reflect the following changes.

Please change or current mailing address of Cardiology Consultants of item #1 East Michigan, 7492 River Road, Flushing, MI, 48433 to Cardiology

Consultants of East Michigan, G-4040 S. Linden Road, Flint, MI, 48507.

Item #2 Please remove Dr. Breece as Radiation Safety Officer (RSO) and add Dr. Brill as our RSO, per our request in our license application dated June 8, 2006 (see enclosed page of application). Dr. Brill was listed as RSO on license #21-32530-01, Cardiology of Michigan.

Thank you for your help in this manner. If you require additional information, please contact our physics consultant, Laura M. Luna at 734-662-3197.

Cordially,

W. Breece, mo

Executive Administration Wayne J. Breece, M.D.





CARDIOLOGY CONSULTANTS OF EAST MICHIGAN

G-4040 S. Linden Rd. Flint, MI 48507 (810) 733-0790 1031 Suncrest Drive Lapeer, MI 48867 (810)664-4870

June 19, 2006

David A. Brill, MD Radiation Safety Officer G-4040 S. Linden Road Flint, MI 48507

RE: Radiation Safety Officer/Executive Management Letter of Understanding

Dear Dr. Brill:

You have been appointed the Radiation Safety Office (RSO) of this facility for our United States Nuclear Regulatory Commission Materials License. This "Letter of Understanding" is prepared to comply with the Title 10 Code of Federal Regulations (CFR)

Part 35.24(b). This section of the regulations requires that you agree in writing to the following:

- > Assume responsibility for implementing the Radiation Protection Program.
- > Ensure that radiation safety activities are being performed in accordance with our own approved procedures and all regulatory requirements.

Furthermore, in compliance with 10 CFR 35.24(d), (g), the executive management of this facility agrees to provide you as RSO:

- Specific written notation of your authority, duties and responsibilities, see attached.
- > Sufficient authority, organizational freedom, time, resources and management prerogative to:
 - 1. Identify radiation safety problems;
 - 2. Initiate, recommend, or provide corrective actions;
 - 3. Stop unsafe operations; and,
 - 4. Verify implementation of corrective actions.

Our signatures noted below will attest to the issues noted above. Please make a copy of this document for your files and return the original to my attention.

Sincerely,

Wayne J. Breece, MD

Executive Management

David A. Brill, MD

Radiation Safety Officer

Cardiology Consultants of East Michigan NRC Byproduct Material License Application June 13, 2006

RADIATION SAFETY PROGRAM RESPONSIBILITY

8.10 Item 7

Radiation Safety Officer

Dr. David A. Brill, M.D.

8.11 Item 7

Authorized Users

Materials

David A. Brill, M.D.

35.100, and 35.200
(excluding Xe-133) limited to cardiovascular clinical procedures


Wayne J. Breece, M.D.

35.100, and 35.200

(excluding Xe-133) limited to

cardiovascular clinical procedures

All named users are currently authorized on the enclosed NRC license.



TUE