NRC FORM 591M PAF	RT 1		U.S. NUCLEAR REGULATORY COMMISSION	
10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
1. LICENSEE/LOCATION INSPECTED: Century Inspection, Inc. P.O. Box 59126 10931 Indian Trail Dallas, Texas 75229-3525 Location: Prudhoe Bay, Alaska			2. NRC/REGIONAL OFFICE USNRC Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005	
REPORT NUMBER(S) 2006-003				
3. DOCKET NUMBER(S) 030-06415		4. LICENSEE NUMBER(S) 42-08456-01	5. DATE(S) OF INSPECTION August 7, 2006	
LICENSEE:			<u> </u>	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X				
I horoby state that within			ve Actions for Item 4, above.	point of
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. Title Printed Name Signature Date				
LICENSEE'S REPRESENTATIVE	7 11111	ou rumo	Oignature	Date
NRC INSPECTOR	Randy Erickson		/RA/	8/7/06