

*Docket File Information*  
**SAFETY INSPECTION REPORT  
AND COMPLIANCE INSPECTION**

1. LICENSEE <b>Midwest Industrial X-ray</b> REPORT NUMBER(S) <b>06-01</b>		2. NRC/REGIONAL OFFICE <b>USNRC Region IV</b>	
3. DOCKET NUMBER(S) <b>030-32629</b>	4. LICENSE NUMBER(S) <b>33-27427-01</b>	5. DATE(S) OF INSPECTION <b>July 17, 2006</b>	
6. INSPECTION PROCEDURES USED <b>87121</b>	7. INSPECTION FOCUS AREAS <b>03.01-03.07</b>		

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) <b>3320</b>	2. PRIORITY <b>1</b>	3. LICENSEE CONTACT <b>Mike Menger</b>	4. TELEPHONE NUMBER <b>701-282-7846</b>
-----------------------------------	-------------------------	---	--

Main Office Inspection      Next Inspection Date: **July 2007**

Field Office \_\_\_\_\_

Temporary Job Site \_\_\_\_\_

**PROGRAM SCOPE**

Mike Menger is President and RSO. Nikki Altringer is the office manager. Currently there are 14 radiographers and 5 assistant radiographers. Work is conducted in North and South Dakota, Minnesota and Iowa. The Minnesota field office was removed from the license when Minnesota became an Agreement state. During the last year from July 2005 to July 2006 there have been 23 jobs in South Dakota. Two new sources were received and 2 sources were disposed. Receipt and disposal records were in order. Instrumentation was properly calibrated at the appropriate frequency. Radiographers were properly training including HAZMAT refresher training. No violations were noted for this inspection.