

CARDIOLOGY
ASSOCIATES OF
CENTRAL
CONNECTICUT, LLC

97 BARNES RD., WALLINGFORD, CT 06492
TEL. 203-284-3137 FAX 203-284-3130

STEPHEN D. ROSSNER, M.D., F.A.C.P.
HAROLD S. WILKES, M.D., F.A.C.C.
GEORGE SPIVACK, M.D., F.A.C.C.
JOHN S. ZESK, M.D., F.A.C.C.

September 8, 2006

J-4
MS-12

2006 SEP 14 AM 10: 27

RECEIVED
REGION 1

Betsy Ullrich
Health Physicist
Commercial and R&D Branch
Division of Nuclear Materials Safety
United States Nuclear Regulatory Commission, Region 1
475 Allendale Road
King of Prussia, PA 19406-1415

Dear Ms. Ullrich:

03036162

I am responding to your letter Mail Control No. 139280, dated August 28, 2006, requesting additional information concerning our application for amendment of license control #139280. Our NRC license number is 06-30788-01. Starting January 1, 2006 the cardiology division of Internal Medicine Associates, P.C. merged their practice with Meriden Wallingford Cardiovascular Associates, LLC., to form a new practice to called Cardiology Associates of Central Connecticut, LLC.

Prior to this merger, both groups had NRC licenses and nuclear cameras. Our NRC license is 06-30788-01. Their nuclear license is 06-30842-01. Our radiation officer is myself, Dr. George Spivack. Their radiation officer is Dr. Robert J. Golub.

Although merged, the two nuclear laboratories have remained clinical independent entities. We have made no changes whatsoever in control of either nuclear license.

The radiation safety officer for license #06-30788-01 remains Dr. George Spivack, and the licensee contact is Laura Schipritt, our office manager. No changes in personnel or duties that relate to the license program are anticipated. There are no new personnel. No changes in the organization, location, facilities, equipment, or procedures are anticipated or planned. The surveillance program will not change.

All records concerning the safe and effective functioning of our laboratory will remain with our laboratory. We will continue to maintain these carefully. We will also abide by all constrains, conditions, requirements, and commitments of the Nuclear Regulatory Commission.

139280
NMSS/RGNI MATERIALS-C02


**CARDIOLOGY
ASSOCIATES OF
CENTRAL
CONNECTICUT, LLC**

STEPHEN D. ROSSNER, M.D., F.A.C.P.
HAROLD S. WILKES, M.D., F.A.C.C.
GEORGE SPIVACK, M.D., F.A.C.C.
JOHN S. ZESK, M.D., F.A.C.C.

Effectively, we have joined together with another cardiology practice in our community. We are now a seven-physician practice. We are not, however, changing or altering control over NRC licenses. The control of NRC license # 06-30788-01 will remain unchanged as will control over license 06-30842-01. We will maintain separate radiation safety officers for each license. We anticipate no changes in any operational aspects of our program.

I hope that this information clarifies the letter you sent. Please let me know if I can help in any way or supply additional information.

Sincerely,



George Spivack, M.D., F.A.C.C.