

<b>U.S. NUCLEAR REGULATORY COMMISSION</b>		Date: 9/15/2006
<b>TELEPHONE CONVERSATION RECORD</b>		Time: 10:00
Mail Control or Report No(s):	N/A	License No(s). 37-30196-01      Docket No(s). 03033750
Name of Licensee:	Burle Industries	
Name of Participant(s):	Scott Moulfoif, Ph.D., Radiation Safety Officer Steven R. Courtemanche, Health Physicist NRC	
Telephone No.	717-296-6043 610-337-5075	
Subject: (NOTE: This will be used as the Documents Title in ADAMS)	Lost source	
Summary:	<p>I left a message on Mr. Moulzoif's voice-mail for him to get back in touch with me about the missing tritiated sealed source.</p> <p>16:45 Mr. Moulzoif called me back. He stated that the missing source was identified while he was backing up the remaining sources for shipment back to the manufacturer for disposal. Previous inventories had not identified the missing source because the licensee was only checking to see if the correct number of lucite blocks were in the storage area. The block with the missing source had not been used in over a year-and-a-half. The licensee's efforts to locate the source were to check the trash and areas of use under low-light conditions because the source phlorescences and was about the size of a grain of rice. All blocks remaining, i.e., 190, were shipped offsite. The licensee is considering terminating the license even though a plant in Mexico still uses the blocks for calibration. (EN 42843)</p>	
Action Required:	Place in ADAMS	
Document Availability:	<input checked="" type="checkbox"/> Publicly Available <input type="checkbox"/> Non-Publicly Available <input checked="" type="checkbox"/> Non-Sensitive <input type="checkbox"/> Non-Sensitive Copyright <input type="checkbox"/> Sensitive <input type="checkbox"/> Sensitive Copyright <input type="checkbox"/> Immediate Release <input checked="" type="checkbox"/> Normal Release <input type="checkbox"/> Delay Release Date	
Prepared & SUNSI Review Completed By:	Steven Courtemanche	/ RA /      Date: 9/17/2006