U.S. NUCLEAR REG	ULATORY COMMISSION	Date: 9/15/2006
TELEPHONE CON	VERSATION RECORD	Time: 10:00
Mail Control N/A or Report No(s).	License No(s). 37-30196-01	Docket No(s). 03033750
Name of Licensee:	Burle Industries	
Name of Participant(s):	Scott Moulfoif, Ph.D., Radiation Safe Steven R. Courtemanche, Health Ph	•
Telephone No.	717-296-6043 610-337-5075	
Subject: (NOTE: This will be used as the Documents Title in ADAMS)	Lost source	
Summary:	I left a message on Mr. Moulzoif's vowith me about the missing tritiated se	
	16:45 Mr. Moulzoif called me back. Was identified while he was backing shipment back to the manufacturer for had not identified the missing source checking to see if the correct number area. The block with the missing source year-and-a-half. The licensee's effort check the trash and areas of use under source phlorescences and was about blocks remaining, i.e., 190, were ship considering terminating the license educes the blocks for calibration. (EN	up the remaining sources for or disposal. Previous inventories because the licensee was only or of lucite blocks were in the storage where had not been used in over a rts to locate the source were to der low-light conditions because the at the size of a grain of rice. All opped offsite. The licensee is even though a plant in Mexico still
Action Required:	Place in ADAMS	
Document Availability:	X Publicly Available	Non-Publicly Available
X Non-Sensitive	Non-Sensitive Copyright Ser	Sensitive Copyright
Immediate Release	X Normal Release	Delay Release Date
Prepared & SUNSI Review Completed	By: Steven Courtemanche / /	RA / Date: 9/17/2006