



GE Energy

David Hinds
Manager, ESBWR
PO Box 780 M/C L60
Wilmington, NC 28402
USA

T 910 675 6363
F 910 362 6363
david.hinds@ge.com

MFN 06-224
Supplement 1

Docket No. 52-010

September 26, 2006

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555-0001

Subject: Reply to Notice of Nonconformance NRC Inspection Report 05200010/2006-201,
dated June 14, 2006 – Supplement 1

In the Reference 1 letter, GE provided its reply to the Reference 2 NRC Inspection Report. The purpose of this letter is to modify the due date of GE's Corrective Action # 4 associated with Nonconformance 2006-201-02. This Corrective Action states: "Revise and issue the ESBWR DCD to reference the correct QA requirements for the ESBWR Project." The due date for this corrective action given in the Reference 1 letter is February 28, 2007. GE now plans to complete this corrective action by October 31, 2006.

If you have any questions, please do not hesitate to contact me.

Sincerely,

A handwritten signature in cursive script that reads "Kathy Sedney for".

David H. Hinds,
Manager, ESBWR

D068

Reference:

1. MFN 06-224, Revision 1, Letter from David H. Hinds to U.S. Nuclear Regulatory Commission, *Reply to Notice of Nonconformance NRC Inspection Report 05200010/2006-201, dated June 14, 2006 – Revision 1, July 21, 2006*
2. MFN 06-193, Letter from U.S. Nuclear Regulatory Commission to David H. Hinds, NRC *Inspection Report 05200010/2006-201 and Notice of Nonconformance, June 14, 2006*

cc: AE Cabbage USNRC (with enclosures)
RP McIntyre USNRC (with enclosures)
GB Stramback GE/San Jose (with enclosures)