



SHIP TO:
 ATTENTION: Melissa Hankins
 SRB TECHNOLOGIES
 2580 Landmark Drive
 Winston-Salem, NC 27103
 Tel: (336)-659-2610
 E-mail: Melissa@srbtechnologies.com

RGA# _____
No Shipment will be accepted without a proper RGA number and UN2911 written on outside of package.
 (A RGA number will be assigned once we receive this completed form.)

Date Issued: _____

Expiration date: _____

Returned Goods Authorization Form-Disposals

FAILURE TO OBSERVE PROPER PROCEDURE LISTED WILL RESULT IN YOUR SHIPMENT BEING RETURNED.

- 1.) Complete this form in its entirety and return it to SRBT.
- 2.) We will return it to you with a proper RGA# assigned to it.
- 3.) All packages and paperwork must be marked with the assigned RGA# and UN2911.
- 4.) A copy of the completed RGA form must be in each package.
- 5.) No more than 10 signs may be packed in one box.
- 6.) This RGA is valid only for the number of signs listed below.
- 7.) One shipment can be made on this RGA#.
- 8.) Under NRC regulations it is your responsibility to notify your state regulator of the transfer of these signs.
- 9.) Shipment must be sent pre-paid.

Contact Name: JIM BERKES
 Bill To: AEROJET CORP.
 Address: 7499 PINE STAKE ROAD
 City: CULPEPER St: VA Zip: 22701

Phone: 540-854-2124
 Fax: 540-854-2002

INSTALLATION ADDRESS

Company Name: AEROJET CORP.
 Address: 7499 PINE STAKE ROAD
 City: CULPEPER State: VA Zip: 22701
 Telephone: 540-854-2000

GOODS TO BE RETURNED: (This information must be provided in its entirety)

Quantity	Description/Mfr.	Date of manufacture	Life 10, 12, 15 or 20 years If unknown an original activity of 21.6 Ci per sign will be used.
1	SRBT/ SAFETY SIGN/ S/N 512600	06/90	MAX 20 CURIES
1	SRBT/ SAFETY SIGN/ S/N 512605	06/90	↓
1	SRBT/ SAFETY SIGN/ S/N 512606	06/90	
1	SRBT/ SAFETY SIGN/ S/N 512623	06/90	

REASON FOR RETURN:

PO # to Credit: CHECK No. 336195
 Original SRBT Invoice #: _____
 Distributor: _____

Returned for Disposal?: Y / N
 New Order Placed?: Y / N
 Date ordered: _____
 PO#: _____

Do not write below this line – This space reserved for SRBT use only

Returned for Disposal:	Y / N	Disposal Fee: _____
Replaced under Warranty:	Y / N	Date Returned: _____

Date Return Received: _____ Signature: _____

SRBT
Returned Goods Authorization (RGA) Form

RGA#

GOODS TO BE RETURNED: (Continued)

Quantity	Description/Mfr.	Date of Manufacture	Life 10, 12, 15, or 20 years If unknown an original activity of 21.6 Ci per sign will be used.
1	SRBT/ SAFETY SIGN/S/N 512616	06/90	MAX. 20 CURIES
1	/S/N 512625	06/90	
1	/S/N 512602	06/90	
1	/S/N 512603	06/90	
1	/S/N 512607	06/90	
1	/S/N 512601	06/90	
1	/S/N 512599	06/90	
1	/S/N 512604	06/90	
1	/S/N 503914	11/89	
1	/S/N 504469	12/89	
1	/S/N 500728	08/89	
1	/S/N 500729	08/89	
1	/S/N 133361	03/90	
1	/S/N 133357	03/90	
1	/S/N 133356	03/90	
1	/S/N 133360	03/90	
1	/S/N 133358	03/90	
1	/S/N 133366	03/90	
1	/S/N 133355	03/90	
1	✓ /S/N 133367	03/90	✓

SRBT
Returned Goods Authorization (RGA) Form

RGA#

GOODS TO BE RETURNED: (Continued)

Quantity	Description/Mfr.	Date of Manufacture	Life 10, 12, 15, or 20 years If unknown an original activity of 21.6 Ci per sign will be used.
1	SRBT/ SAFETY SIGN / S/N 133365	03/90	MAX. 20 CURIES
1	/S/N 133364	03/90	
1	/S/N 133350	03/90	
1	/S/N 133353	03/90	
1	/S/N 133347	03/90	
1	/S/N 133349	03/90	
1	/S/N 133348	03/90	
1	/S/N 133346	03/90	
1	/S/N 133354	03/90	
1	/S/N 133351	03/90	
1	/S/N 123939	06/89	
1	/S/N 123940	06/89	
1	/S/N 500134	07/89	
1	/S/N 530 ⁵⁰³⁹¹⁰	11/89	
1	/S/N 503905	11/89	
1	/S/N 503911	11/89	
1	/S/N 500734	08/89	
1	/S/N 503913	11/89	
1	/S/N 500137	07/89	
1	✓ /S/N 504467	12/89	✓

SRBT
Returned Goods Authorization (RGA) Form

RGA#

GOODS TO BE RETURNED: (Continued)

Quantity	Description/Mfr.	Date of Manufacture	Life 10, 12, 15, or 20 years If unknown an original activity of 21.6 Ci per sign will be used.
1	SRBT/ SAFETY SIGN / S/N 504470	12/89	MAX. 20 CURIES
1	/S/N 500741	08/89	
1	/S/N 500730	08/89	
1	/S/N 500739	08/89	
1	/S/N 500733	08/89	
1	/S/N 500738	08/89	
1	/S/N 500138	07/89	
1	/S/N 504509	12/89	
1	/S/N 504797	12/89	
1	/S/N 500136	07/89	
1	/S/N 500132	07/89	
1	/S/N 500131	07/89	
1	/S/N 512624	06/90	
1	/S/N 500139	07/89	
1	/S/N 500128	07/89	
1	/S/N 503907	11/89	
1	/S/N 504510	12/89	
1	/S/N 500742	08/89	
1	/S/N 500731	08/89	
1	∇ /S/N 500732	08/89	∇

SRBT
Returned Goods Authorization (RGA) Form

RGA#

GOODS TO BE RETURNED: (Continued)

Quantity	Description/Mfr.	Date of Manufacture	Life 10, 12, 15, or 20 years If unknown an original activity of 21.6 Ci per sign will be used.
1	SRBT/ SAFETY SIGN / S/N 500735	08/89	MAX. 20 CURIES
1	/ S/N 500737	08/89	
1	/ S/N 503912	11/89	
1	/ S/N 500135	07/89	
1	/ S/N 504796	12/89	
1	/ S/N 504468	12/89	
1	/ S/N 504795	12/89	
1	/ S/N 500129	07/89	
1	/ S/N 500740	08/89	
1	/ S/N 500133	07/89	
1	V / S/N 500736	08/89	V

AEROJET - ORANGE COUNTY FACILITY
SRBT SAFETY SIGNS

RGA#

GOODS TO BE RETURNED:

BOX NUMBER	S/N	DATE OF MANUFACTURE	MODEL NUMBER
1	512 600	06/90	B100 - U15
1	512 605	06/90	B100 - U15
1	512 606	06/90	B100 - U15
1	512 603	06/90	B100 - U15
1	512 616	06/90	B100 - U15
1	512 625	06/90	B100 - U15
1	512 602	06/90	B100 - U15
1	512 603	06/90	B100 - U15
2	512 607	06/90	B100 - U15
2	512 601	06/90	B100 - U15
2	512 599	06/90	B100 - U15
2	512 604	06/90	B100 - U15
2	503 914	11/89	B100 - U15
2	504 469	12/89	B100 - U15
2	500 728	08/89	B100 - U15
2	500 729	08/89	B100 - U15
3	133 361	03/90	BETALUXE - U10
3	133 357	03/90	BETALUXE - U10
3	133 356	03/90	BETALUXE - U10
3	133 360	03/90	BETALUXE - U10

AEROJET - ORANGE COUNTY FACILITY
SRBT SAFETY SIGNS

RGA#

GOODS TO BE RETURNED:

BOX NUMBER	S/N	DATE OF MANUFACTURE	MODEL NUMBER
3	133 358	03/90	BETALUXE - U10
3	133 366	03/90	
3	133 355	03/90	
3	133 367	03/90	
4	133 365	03/90	
4	133 364	03/90	
4	133 353	03/90	
4	133 350	03/90	
4	133 347	03/90	
4	133 349	03/90	
4	133 348	03/90	
4	133 346	03/90	
5	133 354	03/90	
5	133 351	03/90	V
5	123 940	06/89	BETALUXE - U10
5	123 939	06/89	BETALUXE - U10
5	500 134	07/89	B100 - U15
5	503 910	11/89	B100 - U15
5	503 905	11/89	B100 - U15
5	503 911	11/89	B100 - U15

AEROJET - ORANGE COUNTY FACILITY
SRBT SAFETY SIGNS

RGA#

GOODS TO BE RETURNED:

BOX NUMBER	S/N	DATE OF MANUFACTURE	MODEL NUMBER
6	500 734	08/89	B100 - U15
6	503 913	11/89	
6	500 137	07/89	
6	504 467	12/89	
6	504 470	12/89	
6	500 741	08/89	
6	500 730	08/89	
6	500 739	08/89	
7	500 733	08/89	
7	500 738	08/89	
7	500 138	07/89	
7	504 509	12/89	
7	504 797	12/89	
7	500 136	07/89	
7	500 132	07/89	
7	500 131	07/89	
7	512 624	06/90	
8	500 139	07/89	
8	500 128	07/89	
8	503 907	11/89	V

AEROJET - ORANGE COUNTY FACILITY
SRBT SAFETY SIGNS

RGA#

GOODS TO BE RETURNED:

BOX NUMBER	S/N	DATE OF MANUFACTURE	MODEL NUMBER
8	504510	12/89	B100 - U15
8	500731	08/89	
8	500732	08/89	
8	500735	08/89	
8	500737	08/89	
8	500742	08/89	
9	503912	11/89	
9	500135	07/89	
9	504796	12/89	
9	504468	12/89	
9	504795	12/89	
9	500129	07/89	
9	500740	08/89	
9	500133	07/89	
9	500736	08/89	V