

U.S. NUCLEAR REGULATORY COMMISSION		Date: 10/11/2006
TELEPHONE CONVERSATION RECORD		Time: 1:20 PM
Mail Control or Report No(s).	139419	License No(s). 37-30854-01 Docket No(s). 03036446
Name of Licensee:	Red Rose Cardiology	
Name of Participant(s):	Jack Olley, RSO	
Telephone No.	717-291-9813	
Subject: (NOTE: This will be used as the Documents Title in ADAMS)	RAI, Experience Attribute missing	
Summary:	The experience attribute for Dr. Smith associated with generator elution was not on the NRC form 313A. Mr. Olley stated that he would get Dr. Smith the experience attribute and would submit in an estimated 2 week period.	
Action Required:	Complete the experience attribute of 10 CFR 35.290.	
Document Availability:	<input checked="" type="checkbox"/> Publicly Available <input type="checkbox"/> Non-Publicly Available <input checked="" type="checkbox"/> Non-Sensitive <input type="checkbox"/> Non-Sensitive Copyright <input type="checkbox"/> Sensitive <input type="checkbox"/> Sensitive Copyright <input type="checkbox"/> Immediate Release <input checked="" type="checkbox"/> Normal Release <input type="checkbox"/> Delay Release Date	
Prepared & SUNSI Review Completed By:	Dennis Lawyer	/ R A / Date: 10/11/2006