



a division of Cardiology Consultants, P.A.
www.CardiacDiagnostic.net

RECEIVED
REGION 1

2006 OCT -5 PM 12: 26

- 3105 LIMESTONE ROAD • SUITE 202 • WILMINGTON, DE 19808
(302) 994-6500 • Fax (302) 994-6922
- 3521 SILVERSIDE ROAD • SUITE 1-A • WILMINGTON, DE 19810
(302) 477-6500 • Fax (302) 477-6509
- 1100 FORREST AVE. • DOVER, DE 19904
(302) 672-1890 • Fax (302) 672-1899
- 550 SOUTH DUPONT PLAZA • MILFORD, DE 19963
(302) 422-6050 • Fax (302) 422-6820
- 1606 SAVANNAH RD. • SUITE 3 • LEWES, DE 19958
(302) 644-3822 • Fax (302) 645-1228

Br. 2

October 3, 2006

Licensing Branch
Nuclear Materials Safety Section
Division of Safety and Safeguards
U.S. N.R.C. – Region 1
475 Allendale Road
King of Prussia, PA 19406

NRC License No. 07-27897-01 03029521

Dear License Reviewer:

As per the requirement for amending our current license to reflect the new address of our Lewes office, 16740 King's Highway, Lewes, DE, I am enclosing a copy of the close out survey and wipes for our old office address of 1606 Savannah Road, Suite 3, Lewes, DE. We would like an amendment removing our old facility from the license.

The survey and wipes were performed by AnnMarie Messick, NCT, CNMT and Kimberly Robles, CNMT on October 2, 2006.

Please contact me at 302-452-3462 with any questions. Alternate contacts are Barry Dennenberg, MD (RSO) at 302-421-9721, AnnMarie Messick, NCT, CNMT at 302-994-6500, or Jack Olley of Walter Robinson Associates at 1-800-446-7622.

Thank you.

Sincerely

Phillip Chapman, Jr.
Executive Director
Cardiology Consultants, PA

139521
NMSS/RCNI MATERIALS-002

NRC License No. 07-27897-01

Survey Meter: Ludlum 14C

Serial #: 164877

Last Calibration Date: 04/10/06

Battery Check: Pass

Check Source: 4.0

Background: .02

Survey Results:

Camera Room

Front Left Corner	.02
Back Left Corner	.01
Front Right Corner	.02
Back Left Corner	.01
Center of Room	.02

1st Stress Room

Front Left Corner	.01
Back Left Corner	.01
Front Right Corner	.01
Back Left Corner	.01
Center of Room	.02

2nd Stress Room

Front Left Corner	.01
Back Left Corner	.01
Front Right Corner	.01
Back Left Corner	.01
Center of Room	.01

Injection Chair

Right Side	.01
Left Side	.01

Hot Lab

Dose Calibrator	.02
Countertop	.04
Lead Lined Module	.02
Trash Can Area	.03
Sink	.02

NRC License No. 07-27897-01

Well Counter: Ludlum 2200 Scaler Ratemeter

Serial #: 164586

Last Calibration Date: 1/17/2006

Efficiency 57Co: 26.3%

Background: 739

Wipe Results:

Hot Lab

1.Sink	823
2.Countertop	742
3.Dose Calibrator	732
4.Well Counter Area	736
5. Lead Module	741
6. Trash can	795

Camera Room

7.Front Right Corner	826
8.Back Right Corner	756
9.Front Left Corner	804
10.Back left Corner	812
11. Center of Room	742

Stress Room 1

12.Front Right Corner	757
13.Back Right Corner	783
14.Front Left Corner	806
15.Back Left Corner	779
16. Center of Room	763
17. Treadmill	764
18.Sink	793
19. Counter	784

Stress Room 2

20.Front Right Corner	778
21.Back Right Corner	824
22.Front Left Corner	801
23.Back Left Corner	785
24. Center of Room	784
25. Treadmill	801
26.Sink	824

Prep Room

27. Front Right Corner	790
28. Back Right Corner	839
29. Front Left Corner	791
30. Back Left Corner	811
31. Center	801

Injection Area

32.	824
-----	-----

Bathroom

33. Sink	757
34. Toilet	787

Reading Room

35. Counter	763
36. Door	836

Hallway

37.	784
-----	-----

Wipe size = 100 cm squared

Enclosed: Lab diagram

This is to acknowledge the receipt of your letter/application dated

10/3/2006, and to inform you that the initial processing which includes an administrative review has been performed.

Amendment 07-27897-01 There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 139521.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.