NRC FORM 591M PAI (10-2003)	RT 1		U.S. NUCLEAR REGULATORY COMMISSION		
10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION					
1. LICENSEE/LOCATION INSPECTED: Red Road Cardiology and the Office of Ellen K. Smith, M.D., FACC 2135 Noll Drive, Suite D Lancaster, Pennsylvania 17603 REPORT Nos 2006-001			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER		4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECT	ION
030-36446		37-30854-01	,	Oct 31, 2006+ No	
LICENSEE:					7
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:					
Licensee's Statement of Corrective Actions for Item 4, above. I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.					
Title	· ·	ted Name	•	nature	Date
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Dennis Lawyer		(Jon Za		11/13/06
NRC FORM 591M PART 1 (Rev. by RI 07/06)			- $ -$	ection\R37-30854-01.20060	01.591mpart1.wpd

SUNSI Review Completed By: /RA/ Or Jan

X Public

X Non-Sensitive