

Osteopathic Cardiology Associates
William A. Esper, D.O., FACOI
Kevin Mikielski, D.O.
4002 Schaper Ave, Suite A
Erie PA 16508

November 9, 2006

NMSB 2

RECEIVED
REGION 1
2006 NOV 13 PM 1:31

Licensing Assistance Team
Division of Nuclear Materials Safety
U.S. Nuclear Regulatory Commission, Region I
475 Allendale Road
King of Prussia PA 19406-1415

RE: License No: 37-31143-01

03037180

To Whom It May Concern:

Please amend our license to name Kevin Mikielski, D.O., as the Radiation Safety Officer. Dr. Mikielski is currently listed as an authorized user on our license. Please refer to the enclosed letter from Dr. Walter. Dr. Walter is our current RSO. He should be retained on the license as an authorized user.

If you have any questions, please contact us or our consultant, David Close, at 440-350-1242.

Sincerely,



William A. Esper, D.O.
Owner

Enc.

139720

NMCC/ROH MATERIALS-002


Corscan

740A NW Broad St.
Southern Pines, NC 28387
910-246-0434

05/15/2006

Dear Colleague,

I am the Radiation Safety Officer listed on the NRC Radioactive Materials License of Corscan, license number 32-31038-01. This communication is to confirm that under my supervision Kevin Mikielski, D.O. has successfully completed the training requirements set forth by the Nuclear Regulatory Commission section §35.50, paragraph (e) and in paragraphs (a)(1)(i) and (a)(1)(ii) or (a)(2)(i) and (a)(2)(ii) or (b)(1) or (c)(1) or (c)(2) of that section, and has achieved a level of radiation safety knowledge sufficient to function independently as a Radiation Safety Officer for a medical use licensee.

A handwritten signature in black ink that reads "Steven W. Walter, MD". The signature is written in a cursive, slightly slanted style.

Steven W. Walter, MD

This is to acknowledge the receipt of your letter/application dated

11/9/2006, and to inform you that the initial processing which includes an administrative review has been performed.

☒ ATTEN. 37-31143-01
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

☐ Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 139720.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.