




UNITED STATES ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

1. LICENSEE DEPARTMENT OF THE ARMY U. S. ARMY ELECTRONICS RESEARCH AND DEVELOPMENT LABORATORY FORT MONMOUTH, NEW JERSEY	2. REGIONAL OFFICE U. S. Atomic Energy Commission Region I, Division of Compliance 376 Hudson Street New York, New York 10014
3. LICENSE NUMBER(S) 29-1022-7	4. DATE OF INSPECTION October 13 and 14, 1966 (Reinsp.)
5. INSPECTION FINDINGS <input checked="" type="checkbox"/> A. No item of noncompliance was found. <input type="checkbox"/> B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42 <input type="checkbox"/> C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42 <input type="checkbox"/> D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d) <input type="checkbox"/> E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e) <input type="checkbox"/> F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2) <input type="checkbox"/> G. Storage containers were not properly labeled to show the quantity, date of measurement, or kind of radioactive material in the containers. 10 CFR 20.203(f) (4) <input type="checkbox"/> H. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b) <input type="checkbox"/> I. Form AEC-3 was not properly posted. 10 CFR 20.206(c) <input type="checkbox"/> J. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b) <input type="checkbox"/> K. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d) <input type="checkbox"/> L. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51 <input type="checkbox"/> M. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c) <input type="checkbox"/> N. Records of inventories were not maintained. 10 CFR 34.26 <input type="checkbox"/> O. Utilization logs were not maintained. 10 CFR 34.27 <div style="text-align: right;"> Charles E. Coner (AEC Compliance Inspector)</div>	
6. LICENSEE'S ACKNOWLEDGMENT The AEC Compliance Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days. <div style="display: flex; justify-content: space-between;"><div data-bbox="188 1827 660 1915"> (Date)</div><div data-bbox="660 1764 1597 1915"> (Licensee Representative — Title or Position)</div></div>	