

From: "John McCarthy" <pri_jmccarthy@vcn.com>
To: "Steve Ingle" <single@state.wy.us>
Date: 12/14/2006 10:39:07 AM
Subject: Re: spill of injection fluid at Samith Ranch

Steve,

Please consider this a formal notification that PRI experienced a reportable release of Injection Fluids from I-14 in wellfield I. The release was detected at 11:30 December 13, 2006 by a Satellite Operator. The release was believed to have been caused by the failure of a water trap connection. Approximately 560 gallons of Injection fluid was release, but didn't enter nor threaten the waters of the state. The line was shut down and repaired and returned to service. The uranium content of the fluid was 2.0 ppm and soil samples will be collected and sent out for analysis. Our spill committee will conduct an investigation and consider recommendations for improvement.

A complete report will be completed and submitted within 7 days.

John McCarthy
Safety, Health and Environment

CC: "Paul Michalak" <PXM2@nrc.gov>

Mail Envelope Properties (45817014.EF8 : 5 : 44792)

Subject: Re: spill of injection fluid at Samith Ranch
Creation Date 12/14/2006 10:38:37 AM
From: "John McCarthy" <pri_jmccarthy@vcn.com>
Created By: pri_jmccarthy@vcn.com

Recipients

nrc.gov

TWGWPO01.HQGWDO01

PXM2 CC (Paul Michalak)

state.wy.us

single (Steve Ingle)

Post Office

TWGWPO01.HQGWDO01

Route

nrc.gov

state.wy.us

Files	Size	Date & Time
MESSAGE	800	12/14/2006 10:38:37 AM
TEXT.htm	1530	
Mime.822	4071	

Options

Expiration Date: None
Priority: Standard
ReplyRequested: No
Return Notification: None

Concealed Subject: No
Security: Standard