

Cardiology Associates, Inc.

Masahiro Mori, MD
 William M. Dang, Jr, MD
 A. Jim Terakubo, MD

FAX Notice

Date:	01/19/07
To:	Mr. Roberto J. Torres, Senior Health Physicist U.S. Nuclear Regulatory Commission, Region IV
Fax Number:	817 860-8263
From:	Pat Poe
Subject:	License Amendment Request for RAML Number 53-29211-01 Expedited Request to Change Radiation Safety Officer
Number of Pages Transmitted (including cover page)	2 pages

This communication is intended solely for the individual or the entity to which it is addressed, and may contain information that is privileged, confidential and/or prohibited from disclosure. If the reader of this communication is not the intended recipient, you are hereby notified that any review, dissemination, distribution or copying of this communication is strictly prohibited. If you have received this communication in error, please notify us immediately by telephone. Thank you.

Cardiology Associates, Inc.

Masahiro Mori, MD
William M. Dang, Jr, MD
A. Jim Terakubo, MD

January 19, 2007

Roberto J. Torres
Senior Health Physicist
U.S. Nuclear Regulatory Commission, Region IV
Division of Nuclear Materials Safety
Nuclear Materials Licensing Branch
611 Ryan Plaza Drive, Suite 400
Arlington, Texas, 76011

Re: License Amendment Request for RAML Number 53-29211-01
Expedited Request to Change Radiation Safety Officer

Dear Mr. Torres:

Cardiology Associates Inc, is submitting this amendment request to change the Radiation Safety Officer from Ronald Frick, to Blaine Ikeda. Cardiology Associates Inc. is a nuclear cardiology clinic using Tc99m and Tl-201 radioisotopes.

Blaine Ikeda is currently the Radiation Safety Officer for PharmaRx Hawaii LLC, license number 53-29217-01MD. Thank you for your review of this license amendment, and please do not hesitate to call Pat Poe, my Finance Manager at (808) 521-8211 ext 102, if you have any questions or concerns.

Sincerely,



William M. Dang, Jr., MD
President

Blaine T. Ikeda, PharmD, is RSO of nuclear pharmacy Lic. 53-29217-MD therefore qualifies as RSO for a 35-200 facility such as 53-29211-01.

