

**Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Midwest Brachytherapy Services, Inc. REPORT NUMBER(S) 2007-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-35581	4. LICENSE NUMBER(S) 24-32280-01	5. DATE(S) OF INSPECTION 2/15/2007	
6. INSPECTION PROCEDURES USED 87132	7. INSPECTION FOCUS AREAS 3.1-3.7		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 2231	2. PRIORITY G2	3. LICENSEE CONTACT David Keys M.D. - RSO	4. TELEPHONE NUMBER 314-768-3068
<input checked="checked" type="checkbox"/> Main Office Inspection <input type="checkbox"/> Field Office <input type="checkbox"/> Temporary Job Site			
Next Inspection Date: 2/2009			

PROGRAM SCOPE

The licensee is authorized for possession of licensed material (HDR) through transportation activities only. Once the HDR arrives at its destination, another NRC or Agreement State license receives the RAM, uses and stores the HDR as required. The licensee is authorized to transport two HDR's, the most recent unit had a Ir-192 source installed on 2/15/07. Only two individuals have been authorized to transport the RAM since the last inspection.

Observations and Findings

The inspector interviewed licensee staff and found the individual to have adequate knowledge regarding NRC regulations. The inspector checked all transportation documentation, training documentation, dosimetry records and found they were in compliance with NRC requirements. The inspector also verified that, during transport, licensed material could be properly stored and secured.

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Midwest Brachytherapy Services, Inc.
St. Louis, MI

2. NRC/REGIONAL OFFICE

REGION III
US NUCLEAR REGULATORY COMMISSION
2443 WARRENVILLE ROAD, SUITE 210
LISLE, ILLINOIS 60532

REPORT

2007-001

3. DOCKET NUMBER(S)

030-35581

4. LICENSEE NUMBER(S)

24-32280-01

5. DATE(S) OF INSPECTION

2/15/07

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



1. Based on the inspection findings, no violations were identified.



2. Previous violation(s) closed.



3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):



4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	David J. Keys	David J. Keys	2/15/07
NRC INSPECTOR	Michael M. LaFranco	Michael M. LaFranco	2/15/07