

Originator: CONVERTED DATA**Originator Phone:** 0**Originator Group:** CONVERTED DATA**Operability Required:** N**Supervisor Name:** CONVERTED DATA**Reportability Required:** N**Discovered Date:** 02/23/1997 00:00**Initiated Date:** 02/23/1997 00:00

Condition Description:

TWO CRACKS WERE FOUND IN CORE SPRAY WELD SW8BN (NCR 97-068). IE-80-13 REPORTING IS REQUIRED. ONE CRACK IS 1.8" IN LENGTH AND ONE IS 0.4" IN LENGTH.

Immediate Action Description:**Suggested Action Description:****EQUIPMENT:**Tag NameTag Suffix Name Component Code Process System Code

99

REFERENCE ITEMS:Type CodeDescription

CONVERTED PR

PR.97.9135

Entergy

ADMIN

CR-PNP-1997-09135

Initiated Date: 2/23/1997 0:00

Owner Group : CA&A Staff

Current Contact: SHATAS, A.

Current Significance: D - ADMIN CLOSE

Closed by: SHATAS, A.

3/2/1997 0:00

Summary Description:

TWO CRACKS WERE FOUND IN CORE SPRAY WELD SW8BN (NCR 97-068). IE-80-13 REPORTING IS REQUIRED. ONE CRACK IS 1.8" IN LENGTH AND ONE IS 0.4" IN LENGTH.

Remarks Description:

PR=EF NCR97-068 CORE SPRAY WELD SW8BN IE-80-13

Closure Description:

THIS PR WAS CLOSED TO PR97.9130

Version: 1**Significance Code:** D - ADMIN CLOSE**Classification Code:** NON-SIGNIFICANT**Owner Group:** CA&A Staff**Performed By:** Shatas, Albert A

02/23/1997 00:00

Assignment Description:

SCREEN IAW PROCEDURE 1.3.121

Entergy**CORRECTIVE ACTION****CR-PNP-1997-09135**

CA Number: 1

Group**Name**

Assigned By: CA&A Staff

SHATAS, A.

Assigned To: CA&A Staff

Shatas,Albert A

Subassigned To :

Originated By: SHATAS, A.

2/23/1997 00:00:00

Performed By: SHATAS, A.

2/23/1997 00:00:00

Subperformed By:

Approved By:

Closed By: SHATAS, A.

2/23/1997 00:00:00

Current Due Date: 03/02/1997

Initial Due Date: 03/02/1997

CA Type: GENERAL

Plant Constraint: NONE

CA Description:

SCREEN IAW PROCEDURE 1.3.121

Response:

CONVERTED DATA

Subresponse :

Closure Comments:

Closed Without Comments