

Originator: Macdonald,John B**Originator Group:** Operations Staff**Supervisor Name:** England,Michael D**Discovered Date:** 06/19/2002 03:57**Originator Phone:** 8132**Operability Required:** N**Reportability Required:** N**Initiated Date:** 06/19/2002 05:39**Condition Description:**

Received Blackout Diesel Generator alarm (C3L-A4) several times during 6/19/02 7p-7a shift. Outside operator responded and each time the local alarm Panel C190 Fuel Tank Leakage (D3) alarm was annunciated.

Immediate Action Description:

The outside operator acknowledged the local alarm. An outstanding MR E0000070 was noted. No visual indications of fuel oil leakage were observed. The alarms were reset on each occurrence. The repeated alarms represent a distraction and nuisance to the operating crew.

Suggested Action Description:

It appears the initial condition documented in the MR has worsened. We should revisit the current MR status and accelerate the investigation and repair of the leakage detection system.

EQUIPMENT:Tag NameTag Suffix Name Component Code Process System Code

Initiated Date: 6/19/2002 5:39**Owner Group :**CRG Mgmt**Current Contact:****Current Significance:** D - ADMIN CLOSE**Closed by:** McWilliams,Dorena C

6/20/2002 10:42

Summary Description:**Remarks Description:**

PR=EF BDG C3L-A4 BLACKOUT DIESEL GENERATOR C190 C-190 FUEL TANK LEAKAGE D3 E0000070

Closure Description:

ADMIN CLOSE.

THIS ISSUE WILL BE ADDRESSED BY MRE0000070.

Version: 1

Significance Code: D - ADMIN CLOSE

Classification Code: NON-SIGNIFICANT

Owner Group: CRG Mgmt

Performed By: McWilliams,Dorena C

06/20/2002 10:41

Assignment Description:

Admin Close.

This issue will be addressed by MRE0000070.