



Rio Tinto Energy America
Kennecott Uranium Company
PO Box 1500, 42 Miles NW of Rawlins
Rawlins, Wyoming 82301-1500
Tel: (307) 324-4924 Fax: (307) 324-4925

27 February 2007

Mr. Keith I. McConnell, Deputy Director
Division of Waste Management & Environmental Protection
Office of Federal & State Materials & Environmental Management Programs
11545 Rockville Pike, Mail Stop T7-E18
Rockville, MD 20852

Dear Mr. McConnell:

SUBJECT: Sweetwater Uranium Project – Docket Number 40-8584
Source Material License No. SUA-1350
Annual Corrective Action Program Review and Groundwater Monitoring Report

Enclosed is a CD-ROM containing Kennecott Uranium Company's Annual Corrective Action Program Review for 2006.

The report summarizes all monitoring and mitigation efforts in the area of the tailings cell under the ground water corrective action program as defined in License Condition 11.3 of USNRC Source Materials License SUA-1350 and also contains the ground water monitoring data required to be submitted under License Condition 12.3.

If you have any questions, please do not hesitate to contact me at (307) 328-1476.

Sincerely,

A handwritten signature in cursive script that reads "Oscar A. Paulson".

Oscar A. Paulson
Facility Supervisor

cc: Mr. Mark Thiesse, Wyoming DEQ/WQD
Stephen J. Cohen (2), Project Manager, USNRC
Director – NRC DRSS – Region IV (w/o enclosure)
John Lucas – RTEA, Gillette, WY



Rio Tinto Energy America
Kennecott Uranium Company
PO Box 1500, 42 Miles NW of Rawlins
Rawlins, Wyoming 82301-1500
Tel: (307) 324-4924 Fax: (307) 324-4925

27 February 2007

Mr. Mark Thiesse
GPC West District
Wyoming Department of Environmental Quality
Water Quality Division
250 Lincoln Street
Lander, Wyoming 82520-2848

Dear Mr. Thiesse:

**SUBJECT: Wyoming DEQ Permit to Mine #481
Annual Corrective Action Program Review and Groundwater Monitoring Report**

Enclosed is a CD-ROM containing Kennecott Uranium Company's Annual Corrective Action Program Review for 2006.

The report summarizes all monitoring and mitigation efforts in the area of the tailings cell under the ground water corrective action program as defined in License Condition 11.3 of USNRC Source Materials License SUA-1350 and also contains the ground water monitoring data required to be submitted under License Condition 12.3.

If you have any questions, please do not hesitate to contact me at (307) 328-1476.

Sincerely,

A handwritten signature in cursive script that reads "Oscar A. Paulson".

Oscar A. Paulson
Facility Supervisor

cc: Mr. Mark Moxley, DEQ/LQD (w/o enclosure)
Keith McConnell, Deputy Director, USNRC
Stephen J. Cohen (2), Project Manager, USNRC
Director - NRC DRSS - Region IV (w/o enclosure)
John Lucas - RTEA, Gillette, WY