

**D. Ashley - Re: Oyster Creek License Conditions**

---

**From:** <michaelp.gallagher@exeloncorp.com>  
**To:** <DJA1@nrc.gov>, <michaelp.gallagher@exeloncorp.com>  
**Date:** 03/29/2007 12:36:53 PM  
**Subject:** Re: Oyster Creek License Conditions  
**CC:** <LXL@nrc.gov>, <MAY@nrc.gov>, <RGS@nrc.gov>

---

Mr Ashley

I have reviewed the attached email regarding license conditions that will be in the final safety evaluation report.

AmerGen understands the license conditions and will accept the conditions.

Please contact me if you require any further information.

Mike Gallagher  
Vice president license renewal projects

-----  
Sent from my BlackBerry Wireless Device

----- Original Message -----

From: D. Ashley <DJA1@nrc.gov>  
To: Gallagher, Michael P  
Cc: Louise Lund <LXL@nrc.gov>; Mitzi Young <MAY@nrc.gov>; Robert Schaaf <RGS@nrc.gov>  
Sent: Thu Mar 29 10:01:36 2007  
Subject: Oyster Creek License Conditions

Mr. Gallagher-

The purpose of this email is to advise you that, we will be adding the following license conditions to the final Safety Evaluation Report (SER) for the Oyster Creek Nuclear Generating Station. (OCGS). OCGS has previously committed to these items during the 539th. meeting of the Advisory Committee on Reactor Safeguards (ACRS) and in letters to the Nuclear Regulatory Commission (NRC). The three previous conditions remain unchanged from the updated SER of December 2005.

The following is a summary of the proposed license conditions as they will appear in section 1.7 of the SER, the actual wording may differ slightly in the Operating License to put it into licensing format:

"The fourth license condition requires the applicant to perform full scope inspections of the drywell sand bed region every other refueling outage.

The fifth license condition requires the applicant to monitor drywell trenches every refueling outage to identify and eliminate the sources of water and receive NRC approval prior to restoring the trenches to their original design configuration.

The sixth license condition requires the applicant to perform an engineering study prior to the period of extended operation to identify options to eliminate or reduce the leakage in the OCGS refueling cavity liner.

The seventh license condition requires the applicant to perform a 3-D (dimensional) finite-element analysis of the drywell shell prior to entering the period of extended operation. "

Please advise me at your earliest convenience of your acceptance of the conditions or a request for additional discussions.

regards,

Donnie Ashley  
NRR/DLR/RLRA  
Oyster Creek  
License Renewal Project Manger  
301-415-3191  
djal@nrc.gov

\*\*\*\*\*

This e-mail and any of its attachments may contain Exelon Corporation proprietary information, which is privileged, confidential, or subject to copyright belonging to the Exelon Corporation family of Companies.

This e-mail is intended solely for the use of the individual or entity to which it is addressed. If you are not the intended recipient of this e-mail, you are hereby notified that any dissemination, distribution, copying, or action taken in relation to the contents of and attachments to this e-mail is strictly prohibited and may be unlawful. If you have received this e-mail in error, please notify the sender immediately and permanently delete the original and any copy of this e-mail and any printout.

Thank You.

\*\*\*\*\*

>

**Mail Envelope Properties** (460BEB18.4FF : 11 : 9471)

**Subject:** Re: Oyster Creek License Conditions  
**Creation Date** 03/29/2007 12:35:33 PM  
**From:** <[michaelp.gallagher@exeloncorp.com](mailto:michaelp.gallagher@exeloncorp.com)>  
**Created By:** [michaelp.gallagher@exeloncorp.com](mailto:michaelp.gallagher@exeloncorp.com)

**Recipients**

nrc.gov  
OWGWPO01.HQGWDO01  
DJA1 (D. Ashley)

nrc.gov  
TWGWPO01.HQGWDO01  
LXL CC (Louise Lund)

nrc.gov  
TWGWPO04.HQGWDO01  
MAY CC (Mitzi Young)

nrc.gov  
TWGWPO02.HQGWDO01  
RGS CC (Robert Schaaf).

exeloncorp.com  
michaelp.gallagher

**Post Office**

OWGWPO01.HQGWDO01  
TWGWPO01.HQGWDO01  
TWGWPO04.HQGWDO01  
TWGWPO02.HQGWDO01

**Route**

nrc.gov  
nrc.gov  
nrc.gov  
nrc.gov  
exeloncorp.com

<b>Files</b>	<b>Size</b>	<b>Date &amp; Time</b>
MESSAGE	3287	29 March, 2007 12:35:33 PM
TEXT.htm	4017	
Mime.822	12088	

**Options**

**Expiration Date:** None  
**Priority:** Standard  
**ReplyRequested:** No

**Return Notification:** None

**Concealed Subject:** No

**Security:** Standard

**Junk Mail Handling Evaluation Results**

Message is eligible for Junk Mail handling

This message was not classified as Junk Mail

**Junk Mail settings when this message was delivered**

Junk Mail handling disabled by User

Junk Mail handling disabled by Administrator

Junk List is not enabled

Junk Mail using personal address books is not enabled

Block List is not enabled