

May 1, 2007

Mr. James H. Lash  
Site Vice President  
FirstEnergy Nuclear Operating Company  
Beaver Valley Power Station  
Mail Stop A-BV-SEB1  
P.O. Box 4, Route 168  
Shippingport, PA 15077

SUBJECT: BEAVER VALLEY POWER STATION, UNIT NO. 2 - PRESSURIZER SURGE,  
SPRAY, SAFETY, AND RELIEF NOZZLE WELD SUSCEPTIBILITY TO  
PRIMARY WATER STRESS-CORROSION CRACKING (TAC NO. MD4133)

Dear Mr. Lash:

This letter acknowledges the receipt of information from FirstEnergy Nuclear Operation Company (FENOC) pertaining to the pressurizer surge, spray, safety, and relief nozzle and safe end welds at Beaver Valley Power Station, Unit No. 2.

The discovery, in October 2006, of five circumferential indications in three Alloy 82/182 dissimilar metal (DM) welds on the pressurizer at the Wolf Creek Generating Station (Wolf Creek) raised safety concerns based on the size and location of the indications. At Wolf Creek, three indications were in the pressurizer surge nozzle-to-safe end weld, and two separate indications were in the safety and relief nozzle-to-safe end welds. These findings also indicated that significant concerns might exist with the inspection schedules for addressing the pressurizer weld concerns issued by the industry-sponsored Materials Reliability Program (MRP), in "Primary System Piping Butt Weld Inspection and Evaluation Guideline (MRP-139)."

The Nuclear Regulatory Commission (NRC) is concerned about the pressurizer surge nozzle-to-safe end weld indications, as this is the first time that multiple circumferential primary water stress-corrosion cracking (PWSCC) indications have been identified in a weld. This condition calls into question the degree of safety margin present in past structural integrity evaluations for flawed DM welds susceptible to PWSCC, since multiple stress-corrosion cracking flaws may grow independently and ultimately grow together, significantly reducing the time from flaw initiation to leakage or rupture.

Based on discussions with the NRC staff, licensees of plants susceptible to this condition have committed to enhanced inspection frequency and reactor coolant system leakage monitoring until actions to mitigate the potential of PWSCC in the affected welds have been completed.

J. Lash

- 2 -

In your letter dated January 31, 2007 (Agencywide Documents Access & Management System (ADAMS) Accession Number ML070330595), you stated that the pressurizer surge, spray, safety, and relief nozzle welds containing Alloy 82/182 material have been mitigated through application of full structural weld overlay at Beaver Valley Power Station, Unit No. 2. As a result, your response adequately addresses the concerns that the NRC has at this time regarding PWSCC susceptibility of these welds. This completes the NRC staff efforts on TAC NO. MD4133 for the review associated with this issue. If you have question regarding this matter, please contact the Beaver Valley Project Manager, Nadiyah S. Morgan at 301-415-1016.

Sincerely,

*/RA/*

Catherine Haney, Director  
Division of Operating Reactor Licensing  
Office of Nuclear Reactor Regulation

Docket No. 50-412

cc: See next page

J. Lash

- 2 -

In your letter dated January 31, 2007 (Agencywide Documents Access & Management System (ADAMS) Accession Number ML070330595), you stated that the pressurizer surge, spray, safety, and relief nozzle welds containing Alloy 82/182 material have been mitigated through application of full structural weld overlay at Beaver Valley Power Station, Unit No. 2. As a result, your response adequately addresses the concerns that the NRC has at this time regarding PWSCC susceptibility of these welds. This completes the NRC staff efforts on TAC NO. MD4133 for the review associated with this issue. If you have question regarding this matter, please contact the Beaver Valley Project Manager, Nadiyah S. Morgan at 301-415-1016.

Sincerely,

*/RA/*

Catherine Haney, Director  
Division of Operating Reactor Licensing  
Office of Nuclear Reactor Regulation

Docket No. 50-412

cc: See next page

Distribution:

PUBLIC	LPL1-1 R/F	RidsNrrPMNMorgan
RidsNrrLASLittle	RidsNrrDorlLpl1-1	RidsOgcRp
RidsAcrsAcnwMailCenter	RidsRgn1MailCenter	RidsNrrDorl
RidsNrrDci	ESullivan, NRR	TLupold, NRR
RidsNrrDciCpnb	PCataldo, Region I	

ADAMS Accession No. ML071020514

OFFICE	CPNB	LPL1-1/PM	LPL1-1/LA
NAME	TLupold	NMorgan	SLittle
DATE	4/30/07	4/23/07	4/19/07
OFFICE	LPL1-1/BC	CPNB/BC	DORL/D
NAME	MKowal	TChan	CHaney
DATE	5/01/07	4/30/07	5/01/07

**OFFICIAL RECORD COPY**

Beaver Valley Power Station, Unit Nos. 1 and 2

cc:

Joseph J. Hagan  
Senior Vice President of Operations  
and Chief Operating Officer  
FirstEnergy Nuclear Operating Company  
Mail Stop A-GO-14  
76 South Main Street  
Akron, OH 44308

James H. Lash  
Senior Vice President of Operations  
and Chief Operating Officer  
FirstEnergy Nuclear Operating Company  
Mail Stop A-GO-14  
76 South Main Street  
Akron, OH 44308

Danny L. Pace  
Senior Vice President, Fleet Engineering  
FirstEnergy Nuclear Operating Company  
Mail Stop A-GO-14  
76 South Main Street  
Akron, OH 44308

Jeannie M. Rinckel  
Vice President, Fleet Oversight  
FirstEnergy Nuclear Operating Company  
Mail Stop A-GO-14  
76 South Main Street  
Akron, OH 44308

David W. Jenkins, Attorney  
FirstEnergy Corporation  
Mail Stop A-GO-18  
76 South Main Street  
Akron, OH 44308

Manager, Fleet Licensing  
FirstEnergy Nuclear Operating Company  
Mail Stop A-GO-2  
76 South Main Street  
Akron, OH 44333

Ohio EPA-DERR  
ATTN: Zack A. Clayton  
P.O. Box 1049  
Columbus, OH 43266-0149

Director, Fleet Regulatory Affairs  
FirstEnergy Nuclear Operating Company  
Mail Stop A-GO-2  
76 South Main Street  
Akron, Ohio 44333

Manager, Site Regulatory Compliance  
FirstEnergy Nuclear Operating Company  
Beaver Valley Power Station  
Mail Stop A-BV-A  
P.O. Box 4, Route 168  
Shippingport, PA 15077

Richard Anderson  
Vice President, Nuclear Support  
FirstEnergy Nuclear Operating Company  
Mail Stop A-GO-14  
Akron, Ohio 44308

Commissioner James R. Lewis  
West Virginia Division of Labor  
749-B, Building No. 6  
Capitol Complex  
Charleston, WV 25305

Director, Utilities Department  
Public Utilities Commission  
180 East Broad Street  
Columbus, OH 43266-0573

Director, Pennsylvania Emergency  
Management Agency  
2605 Interstate Dr.  
Harrisburg, PA 17110-9364

Beaver Valley Power Station, Unit Nos. 1 and 2 (continued)

cc:

Dr. Judith Johnsrud  
Environmental Coalition on Nuclear Power  
Sierra Club  
433 Orlando Avenue  
State College, PA 16803

Director  
Bureau of Radiation Protection  
Pennsylvania Department of  
Environmental Protection  
Rachel Carson State Office Building  
P.O. Box 8469  
Harrisburg, PA 17105-8469

Mayor of the Borough of Shippingport  
P.O. Box 3  
Shippingport, PA 15077

Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 298  
Shippingport, PA 15077