

May 2, 2007

Mr. R. T. Ridenoure
Vice President - Chief Nuclear Officer
Omaha Public Power District
Fort Calhoun Station FC-2-4 Adm.
Post Office Box 550
Fort Calhoun, NE 68023-0550

SUBJECT: FORT CALHOUN STATION, UNIT 1 - PRESSURIZER SURGE, SPRAY,
SAFETY, AND RELIEF NOZZLE WELD SUSCEPTIBILITY TO PRIMARY
WATER STRESS-CORROSION CRACKING (TAC NO. MD4153)

Dear Mr. Ridenoure:

This letter acknowledges the receipt of information from Omaha Public Power District pertaining to the pressurizer surge, spray, safety, and relief nozzle and safe end welds at Fort Calhoun Station, Unit 1.

The discovery, in October 2006, of five circumferential indications in three Alloy 82/182 dissimilar metal (DM) welds on the pressurizer at the Wolf Creek Generating Station (Wolf Creek) raised safety concerns based on the size and location of the indications. At Wolf Creek, three indications were in the pressurizer surge nozzle-to-safe end weld, and two separate indications were in the safety and relief nozzle-to-safe end welds. These findings also indicated that significant concerns might exist with the inspection schedules for addressing the pressurizer weld concerns issued by the industry-sponsored Materials Reliability Program (MRP), in "Primary System Piping Butt Weld Inspection and Evaluation Guideline (MRP-139)."

The U.S. Nuclear Regulatory Commission (NRC) is concerned about the pressurizer surge nozzle-to-safe end weld indications, as this is the first time that multiple circumferential primary water stress-corrosion cracking (PWSCC) indications have been identified in a weld. This condition calls into question the degree of safety margin present in past structural integrity evaluations for flawed DM welds susceptible to PWSCC, since multiple stress-corrosion cracking flaws may grow independently and ultimately grow together, significantly reducing the time from flaw initiation to leakage or rupture.

Based on discussions with the NRC staff, licensees of plants susceptible to this condition have committed to enhanced inspection frequency and reactor coolant system leakage monitoring until actions to mitigate the potential of PWSCC in the affected welds have been completed.

In your letter dated January 31, 2007 (Agencywide Documents Access and Management System (ADAMS) Accession Number ML070320251), you stated that the pressurizer at Fort Calhoun Station was replaced with a component that uses resistant materials and contains no Alloy 82/182 dissimilar metal butt welds. As a result, your response adequately addresses the concerns that the NRC has at this time regarding PWSCC susceptibility of these welds.

R. T. Ridenoure

-2-

This completes the NRC staff efforts on TAC No. MD4153 for the review associated with this issue. If you have any questions regarding this matter, please contact the Project Manager, Alan Wang, at (301) 415-1445.

Sincerely,

/RA/

Catherine Haney, Director
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-285

cc: See next page

R. T. Ridenoure

-2-

This completes the NRC staff efforts on TAC No. MD4153 for the review associated with this issue. If you have any questions regarding this matter, please contact the Project Manager, Alan Wang, at (301) 415-1445.

Sincerely,
/RA/

Catherine Haney, Director
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-285

cc: See next page

DISTRIBUTION:

PUBLIC
RidsNrrLALFeizollahi
RidsAcrsAcnwMailCenter
RidsNrrDci
RidsNrrDciCpnb
RidsNrrDorlLp4 (THiltz)

LPLIV R/F
RidsNrrDorlLp4
RidsRgn4MailCenter
RidsOEMailCenter
ESullivan, NRR

RidsNrrPMAWang
RidsOgcRp
RidsNrrDorl
RidsEdoMailCenter
TLupold, NRR

ADAMS Accession No. ML071060005

OFFICE	CPNB	NRR/LPL4/PM	NRR/LPL4/LA
NAME	TLupold	AWang	LFeizollahi
DATE	4/30/07	4/18/07	4/17/07
OFFICE	NRR/LPL4/BC	CPNB/BC	DORL/D
NAME	THiltz	TChan	CHaney
DATE	5/2/07	4/30/07	5/1/07

OFFICIAL RECORD COPY

Ft. Calhoun Station, Unit 1

cc:

Winston & Strawn
ATTN: James R. Curtiss, Esq.
1700 K Street, N.W.
Washington, DC 20006-3817

Chairman
Washington County Board of Supervisors
P.O. Box 466
Blair, NE 68008

Mr. John Hanna, Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 310
Fort Calhoun, NE 68023

Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-4005

Ms. Julia Schmitt, Manager
Radiation Control Program
Nebraska Health & Human Services R & L
Public Health Assurance
301 Centennial Mall, South
P.O. Box 95007
Lincoln, NE 68509-5007

Mr. David J. Bannister, Manager
Fort Calhoun Station
Omaha Public Power District
Fort Calhoun Station FC-1-1 Plant
P.O. Box 550
Fort Calhoun, NE 68023-0550

Mr. Joe L. McManis
Manager - Nuclear Licensing
Omaha Public Power District
Fort Calhoun Station FC-2-4 Adm.
P.O. Box 550
Fort Calhoun, NE 68023-0550

Mr. Daniel K. McGhee
Bureau of Radiological Health
Iowa Department of Public Health
Lucas State Office Building, 5th Floor
321 East 12th Street
Des Moines, IA 50319

April 2006