

RECEIVED
REGION 1

07 MAY -7 PM 1:44

Med 1

April 26, 2007

Licensing Assistant Section
US. Nuclear Regulatory Commission, Region 1
475 Allendale Road
King of Prussia, PA 19406-1415

Dear Sirs:


030-01265


Please amend License number 06-06697-02 for Stamford Hospital to add Gadolinium Sealed Sources Model IPL: NES-8412 or NAS: MED3601. We will require a maximum of four sources, two in our large Field of View Camera's Vantage option for Attenuation Correction and two in the event of a source exchange. Each source would be approximately 250 mCi, not to exceed 300 mCi with a maximum possession limit of 1 Curie.

We have enclosed a copy of the Camera Manufacturers specifications including the device and sealed source registration numbers.

We appreciate your attention to the above.

Sincerely,


James Summers, M.S.
Radiation Safety Officer


Kathleen Silard
Executive Vice President and
Chief Operations Officer

1404-97

Vantage

If you have purchased the Vantage option for large F-O-V cameras, amend your radioactive materials license to include Gd-153. The Vantage option adds two Gd-153 sealed sources to the Vantage-equipped gamma camera. Use the information in the table below for this source material.

DEVICE		
Manufacturer and Distributor	ADAC Laboratories A Philips Medical Systems Company 540 Alder Drive Milpitas, CA, 95035	Contact: RSO 408-321-9100
Model Name	Vantage	
Registration Number	CA0102D101S	
SEALED SOURCE		
Manufacturer and Distributor	Isotope Products Laboratories (IPL) An Eckert & Ziegler Company 24937 Avenue Tibbitts Valencia, CA 91355	661-309-1010 661-257-8303 (fax)
	North American Scientific (NAS) 7435 Greenbush Road North Hollywood, CA 91605	818-503-9201 818-503-0846 (fax)
Quantity	2 per system	
Type	Attenuation correction source	
Model Number	IPL: NES-8412 NAS: MED3601	
Registration Number	IPL: CA0406S204S NAS: CA0510S121S	
Radionuclide	Gadolinium-153	
Single Source Strength	250 mCi, not to exceed 300 mCi	
Maximum Possession Limit	1 Ci	

This is to acknowledge the receipt of your letter/application dated

4/26/2007, and to inform you that the initial processing which includes an administrative review has been performed.

Answer. 06-06697-02 There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 140497.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.