

**Request for Additional Information
AREVA NP, Inc.
Lynchburg, VA**

Docket No.: 70-1201
License No.: SNM-1168

Decommissioning Funding Plan

Please provide the following information concerning your Decommissioning Funding Plan (DFP), dated March 6, 2007:

The DFP does not contain sufficient detail to determine if contractor profit was included in the labor cost estimate. Therefore, the DFP should be supplemented to either: (1) explain how contractor profit was included, or (2) revise the cost estimate to include contractor profit.

This information is required to determine compliance with 10 CFR 70.25(e), which requires that each decommissioning funding plan contain a cost estimate for decommissioning. NUREG-1757, "Consolidated NMSS Decommissioning Guidance: Financial Assurance, Recordkeeping, and Timeliness," Vol. 3, App. A.3.1.2.1 provides guidance on complying with 10 CFR 70.25 and states that the labor cost estimate should include contractor profit.

Enclosure