Buchanan Ingersoll & Rooney PC

Attorneys & Government Relations Professionals

One South Market Square 213 Market Street, 3rd Floor Harrisburg, PA 17101-2121

P.O. Box 12023 Harrisburg, PA 17101-2023 T 717 237 4800 F 717 233 0852 www.buchananingersoll.com

Carol Brayshaw Longwell 717 237 4833 carol.longwell@bipc.com

May 30, 2007

MMS 81

United States Nuclear Regulatory Commission Attention: Licensing Assistance Team Region 1 – 475 Allendale Road King of Prussia, Pennsylvania 19406 VIA FACSIMILE (610) 337-5269 ORIGINAL VIA OVERNIGHT MAIL

Pennsylvania Department of Environmental Protection Bureau of Radiation Protection Radioactive Materials Licensing Section Rachel Carson State Office Building 400 Market Street Harrisburg, Pennsylvania 17101 VIA FACSIMILE (717) 783-8965 ORIGINAL VIA OVERNIGHT MAIL SE OF IN 15 AW DE 39

REGION 1

Re: Roxborough Memorial Hospital 37-13952-01 (03003208)
Warminster Hospital 37-18263-01 (03014750)

To Whom It May Concern:

Enclosed is a letter of notice from Solis Healthcare, LP regarding the projected change of ownership of Roxborough Memorial Hospital in Philadelphia, Pennsylvania, and Warminster Hospital in Bucks County, Pennsylvania. The letter includes the information we understand that your agencies require to effect a change of ownership. If you require additional information, please call me at (717) 237-4833. Thank you for your assistance with these changes of ownership.

Yours sincerely,

Carol Brayshaw Longwell

CBL/ldwm Enclosure

140578/140579

#1010823-v1

NMSS/RGN1 MATERIALS-002

United States Nuclear Regulatory Commission Attn: Licensing Assistance Team Region 1 – 475 Allendale Road King of Prussia, PA 19406 VIA FACSIMILE (610) 337-5269 ORIGINAL VIA OVERNIGHT MAIL

Pennsylvania Department of Environmental Protection Bureau of Radiation Protection Radioactive Materials Licensing Section Rachel Carson State Office Building P.O. Box 8469 Harrisburg, PA 17105-8469 VIA FACSIMILE (717) 783-8965 ORIGINAL VIA OVERNIGHT MAIL

Re: Roxborough Memorial Hospital Warminster Hospital

To Whom It May Concern:

Solis Healthcare, LP, a Delaware limited partnership, writes to advise the Pennsylvania Department of Environmental Protection, Bureau of Radiation Protection, Radiation Control Division ("DEP") and the Nuclear Regulatory Commission ("NRC"), of the projected change of ownership of Roxborough Memorial Hospital ("Roxborough") in Philadelphia, Pennsylvania, and Warminster Hospital ("Warminster") in Bucks County, Pennsylvania. On July 1, 2007, Solis Healthcare, LP will acquire substantially all of the assets and business of Tenet HealthSystem Roxborough, LLC, the owner and operator of Roxborough Memorial Hospital, and Tenet HealthSystem Bucks County, L.L.C., the owner and operator of Warminster Hospital ("Tenet").

Roxborough Memorial Hospital currently holds the following NRC and DEP licenses:

DEP	(Radiation Producing Machines)	10-01462	(expiration date: 10/31/07)
DEP	(Radioactive Material)	PA-0116	(expiration date: 2/28/14)
NRC		37-13952-01	(expiration date: 10/30/09)

Warminster Hospital currently holds the following NRC and DEP licenses:

DEP	(Radiation Producing Machines)	10-08558	(expiration date: 9/30/07)
DEP	(Radioactive Material)	PA-0378	(expiration date: 2014)
NRC		37-18263-01	(expiration date: 11/13/15)

Solis Healthcare, LP, the new owner, is a newly formed entity based in Philadelphia, Pennsylvania. Its management team includes Robert G. Souaid and John J. Donnelly, Jr. Mr. Souaid has been active in the health care industry and an owner of various health care properties for the past twelve years. Mr. Donnelly has thirty-five years of health care experience, and for the past seventeen years has been the Chief Executive Officer of Roxborough, in which capacity he will continue after the change of ownership. Kathleen M. Farrell, the current administrator of Warminster, will also continue in that position after the change of ownership.

Both hospitals will continue to operate at their existing locations under the current names. It is anticipated that the organizational and administrative structures within both hospitals will remain substantially the same. In fact, Solis Healthcare has agreed with Tenet to employ substantially all of the current employees of Roxborough and Warminster, and the personnel having control over licensed activities subject to the agencies' oversight are expected to remain the same. Solis Healthcare is committed to provide the highest quality care possible to its patients and will abide by all applicable rules and regulations.

After the change of ownership, it is anticipated that there will not be any substantial change in the facilities, equipment or procedures subject to the agencies' oversight. It is further anticipated that there will not be any change in the use, possession, location or storage of licensed materials. Tenet has represented that the applicable records will be transferred to Solis Healthcare on July 1, 2007, and Solis Healthcare will maintain the records in substantially the same manner as before the change of ownership.

According to the attached summaries from Kent Lambert, Director of Radiation Safety for both hospitals, there are no contamination or ambient radiation levels on site at either facility and there are not any open inspection and enforcement issues. Further, all surveillance items and records are presently current and will be current at the time of transfer.

DEP completed an equipment inspection at Warminster Hospital on May 16 and 17, 2007. The NRC completed its inspection at Warminster on April 12, 2007. There were no violations cited in either inspection.

The license contact person at both facilities will remain the same. In the case of Roxborough Memorial, the license contact person will continue to be Tina Scott. Her telephone number is (215) 487-4503. At Warminster, the license contact person will continue to be Beth A. Prajzner. Her telephone number is (215) 441-6816.

Attachments

If you require further information to transfer these licenses, please contact either Ms. Scott or Ms. Prazner.

Tenet HealthSystem Roxborough, L.L.C. By: John J. Donnelly, Jr. Chief Executive Officer	Robert G. Souaid Manager of the General Partner of Solis Healthcare, LP
Tenet HealthSystem Bucks County, L.L.C.	
By: Kathleen M. Farrell Interim Chief Executive Officer	

If you require further information to transfer these licenses, please contact either Ms. Scott or Ms. Prajzner.

Tenet HealthSystem Roxborough, L.L.C.	
	Robert G. Souaid
By:	Manager of the General Partner of
John J. Donnelly, Jr.	Solis Healthcare, LP

Tenet HealthSystem Bucks County, L.L.C.

Chief Executive Officer

Kathleen M. Farrell

Interim Chief Executive Officer

Attachments

If you require further information to transfer these licenses, please contact either Ms. Scott or Ms. Prazner.

Tenet HealthSystem Roxborough, L.L.C.

John J. Donnelly, Jr.

Chief Executive Officer

Robert G. Souaid

Manager of the General Partner of

Solis Healthcare, LP

Tenet HealthSystem Bucks County, L.L.C.

By:_____

Kathleen M. Farrell Interim Chief Executive Officer

Attachments

Dear Ms. Prajzner:

This is in response to your request for information necessary for the transfer of the byproduct material license issued by the U.S. Nuclear Regulatory Commission and the naturally occurring and accelerator produced radioactive material license issued by the Commonwealth of Pennsylvania, Department of Environmental Protection, Bureau of Radiation Protection, from Tenet to Solis.

- 1. No, changes to the nuclear medicine technologist staff does not matter. Only changes to authorized users, radiation safety officer, and other individuals specifically listed on the license (e.g., some licensees have authorized medical physicists and authorized nuclear pharmacists specifically listed). That you are planning to continue with the same Radiologists means that you can respond that there is no change to authorized users and Radiation Safety Officer.
 - 2. All surveillance items have been completed and are up to date.
 - A physical inventory of all sealed sources was performed 2/15/07 and again on 5/18/07. Although performed quarterly, 10 CFR 35.67(g) requires that this be performed semiannually. The location of all sources was verified and documented. No corrective actions required.
 - Leak tests of all sealed sources for which leak tests are required was last performed 2/15/07. 10 CFR 35.67(b)(2) requires that this be performed semiannually. No sources were leaking. No corrective actions required.
 - Daily and weekly radiological surveys are on-going. Independent surveys are conducted quarterly. Last independent survey was conducted 5/18/07.
 - Quality assurance tests on the dose calibrator are up to date. These tests were last performed as follows:
 - Linearity of response test last performed: 5/18/07 (analysis not complete). Due again: August 2007
 - Accuracy test last performed: 8/28/2006. Measurements were within acceptable tolerances. Due again: August 2007
- 3. Upon request, we will transfer any records we have to Tenet for subsequent transfer to Solis. If Solis plans to continue to utilize our services, we will retain the records for Solis, effectively transferring them by contract.
 - 4. There are no known sites with either fixed or removable contamination.
- 5. There are no open inspection items or enforcement actions from the last NRC inspection.

6. The license is being transferred and licensed activities will continue; therefore, the facility will not be decommissioned.

Kent Lambert, M.S., CHP Director, Radiation Safety

Dear Ms. Scott:

This is in response to your request for information necessary for the transfer of the byproduct material license issued by the U.S. Nuclear Regulatory Commission and the naturally occurring and accelerator produced radioactive material license issued by the Commonwealth of Pennsylvania, Department of Environmental Protection, Bureau of Radiation Protection, from Tenet to Solis.

- 1. All surveillance items have been completed and are up to date.
 - A physical inventory of all sealed sources was performed 2/12/07 and again on 5/4/07. Although performed quarterly, 10 CFR 35.67(g) requires that this be performed semiannually. The location of all sources was verified and documented. No corrective actions required.
 - Leak tests of all sealed sources for which leak tests are required was last performed 2/12/07. 10 CFR 35.67(b)(2) requires that this be performed semiannually. No sources were leaking. No corrective actions required.
 - Daily and weekly radiological surveys are on-going. Independent surveys are conducted quarterly. Last independent survey was conducted 5/18/07.
 - Quality assurance tests on the dose calibrator are up to date. All measurements were within acceptable tolerances. These tests were last performed as follows:
 - Linearity of response test last performed: 4/5/07. Due again: July 2007
 - Accuracy test last performed: 11/28/06. Due again: November 2007
- 2. Upon request, we will transfer any records we have to Tenet for subsequent transfer to Solis. If Solis plans to continue to utilize our services, we will retain the records for Solis, effectively transferring them by contract.
 - 3. There are no known sites with either fixed or removable contamination.
- 4. There are no open inspection items or enforcement actions from the last NRC inspection.
- 5. The license is being transferred and licensed activities will continue; therefore, the facility will not be decommissioned.

Kent Lambert, M.S., CHP Director, Radiation Safety