


UNITED STATES ATOMIC ENERGY COMMISSION  
DIVISION OF COMPLIANCE

JUN 6 1963

## INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

1. LICENSEE <b>Union Carbide Olefins Company Special Instrumentation Division 437 MacCorkle Avenue South Charleston, West Virginia</b>	2. REGIONAL OFFICE <b>U. S. Atomic Energy Commission Region II, Division of Compliance 50 Seventh Street, N. E. Atlanta 23, Georgia</b>
3. LICENSE NUMBER(S) <b>47-260-2</b>	4. DATE OF INSPECTION <b>April 23-25, 1963</b>
5. INSPECTION FINDINGS <input checked="" type="checkbox"/> A. No Item of noncompliance was found. <input type="checkbox"/> B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(h) or 31.302 <input type="checkbox"/> C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c)(1) or 31.302 <input type="checkbox"/> D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d) <input type="checkbox"/> E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e) <input type="checkbox"/> F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f)(1) or (f)(2) <input type="checkbox"/> G. Storage containers were not properly labeled to show the quantity, date of measurement, or kind of radioactive material in the containers. 10 CFR 20.203(f)(4) <input type="checkbox"/> H. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b) <input type="checkbox"/> I. Form AEC-3 was not properly posted. 10 CFR 20.206(c) <input type="checkbox"/> J. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 31.203(b) <input type="checkbox"/> K. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 31.303(d) <input type="checkbox"/> L. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.41, 40.61 or 70.51 <input type="checkbox"/> M. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 31.105(c). <input type="checkbox"/> N. Records of inventories were not maintained. 10 CFR 31.106 <input type="checkbox"/> O. Utilization logs were not maintained. 10 CFR 31.107	
<div style="text-align: right;"> (AEC Compliance Inspector)</div>	
6. LICENSEE'S ACKNOWLEDGMENT The AEC Compliance Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days.  <div style="display: flex; justify-content: space-between;"><div>(Date) _____</div><div>(Licensee Representative—Title or Position) _____</div></div>	

COPIES: ☐ LICENSEE: ☒ COMPLIANCE REGION: ☐ DIV. OF LIC. & REG.: ☐ DIV. OF COMPLIANCE

I-H, II Reinspection (1)

A-17