

JUN 6 1963

Union Carbide Corporation
Technical Center
South Charleston, West Virginia

Attention: Mr. N. H. Ketchan
Radiation Protection Officer

Gentlemen:

Enclosed are three forms AEC-591, "Inspection Findings and Licensee Acknowledgment", showing that no items of noncompliance were noted during the recent inspection of the programs conducted under License Nos. 47-260-2, 47-260-3, and 47-260-4. Please retain these inspection findings with valuable paper concerning your isotope program.

Forms AEC-591 covering the programs at the South Charleston plant, License No. 47-260-7, and the Institute Plant, License 47-4373-1, were issued at the time of the inspection. A report of the inspection findings relative to the program conducted under License No. 47-260-6 will be covered in separate correspondence. As you will recall, there were discrepancies associated with this latter program concerning the incineration of tritium and the maintenance of survey records where carbon-14 and tritium were used.

Thank you for your cooperation.

Sincerely yours,

W. P. Ellis
Radiation Specialist

Enclosures:
AEC-591 as stated

OFFICE ▶	CO:II:pws					
SURNAME ▶	Ellis <i>WPE</i>					
DATE ▶						

A-18