


INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

<p>1. LICENSEE Union Carbide Corporation Union Carbide Olefins Company Division 437 Mac Corkle Avenue South Charleston, West Virginia</p>	<p>2. REGIONAL OFFICE U. S. Atomic Energy Commission Region II, Division of Compliance 290 Peachtree St., N. W., Suite 818 Atlanta, Georgia 30303</p>
<p>3. LICENSE NUMBER(S) 47-269-2</p>	<p>4. DATE OF INSPECTION September, 28-29, 1970</p>
<p>5. INSPECTION FINDINGS</p> <p><input checked="" type="checkbox"/> A. No item of noncompliance was found.</p> <p><input type="checkbox"/> B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42</p> <p><input type="checkbox"/> C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42</p> <p><input type="checkbox"/> D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)</p> <p><input type="checkbox"/> E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)</p> <p><input type="checkbox"/> F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)</p> <p><input type="checkbox"/> G. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)</p> <p><input type="checkbox"/> H. Form AEC-3 was not properly posted. 10 CFR 20.206(c)</p> <p><input type="checkbox"/> I. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)</p> <p><input type="checkbox"/> J. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)</p> <p><input type="checkbox"/> K. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51</p> <p><input type="checkbox"/> L. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)</p> <p><input type="checkbox"/> M. Records of inventories were not maintained. 10 CFR 34.26</p> <p><input type="checkbox"/> N. Utilization logs were not maintained. 10 CFR 34.27</p> <div style="text-align: right; margin-top: 20px;">  _____ (AEC Compliance Inspector) </div>	
<p>6. LICENSEE'S ACKNOWLEDGMENT</p> <p>The AEC Compliance Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days.</p> <div style="display: flex; justify-content: space-between; margin-top: 20px;"> <div style="width: 40%; border-top: 1px solid black; text-align: center;"> _____ (Date) </div> <div style="width: 55%; border-top: 1px solid black; text-align: center;"> _____ (Licensee Representative - Title or Position) </div> </div>	

ORIGINAL: LICENSEE. COPIES: CO HEADQUARTERS CO ENFORCEMENT CO REGION

E, III, Reinspection (2), 10/73-A-35