

J. T. Sutherland, Acting Chief, Radiological and Environmental
Protection Branch, Region II, Directorate of Regulatory Operations

INSPECTOR'S EVALUATION AND OPINION - UNION CARBIDE CORPORATION,
SOUTH CHARLSTON, WEST VIRGINIA, LICENSE NO. 47-260-2

The licensee's use of licensed material has not resulted in a health or safety problem. No unusual occurrence has been encountered. Personnel appear to be well-qualified and trained in handling radioactive material in a safe manner. The licensee's procedures and method of handling radioactive material, attest to the fact that there has not been any significant problem involving the use of licensed material. Licensed material has been secured against unauthorized removal.

H. W. Young
H. W. Young
Radiation Specialist

PG
6/14/73

A-43