

Edwards

JUL 30 1963

Eber R. Price, Assistant Director
Division of Licensing and Regulation

Leo Dubinski, Assistant Director for Materials
Division of Compliance

Original Signed by
Leo Dubinski

COMPLIANCE INSPECTION REPORT FOR UNION CARBIDE CHEMICALS
COMPANY, SOUTH CHARLESTON, WEST VIRGINIA; INSPECTION
CONDUCTED ON APRIL 23 - 25, 1963 - LICENSE NO. 47-260-6

CO:WBJ


In response to R. G. Page's memorandum of July 19, 1963,
subject as above, we have contacted Region II, Division
of Compliance. They have informed us that the reference
to three-year leak tests in paragraph 37 of the report
is an error and should be disregarded; the licensee was
in compliance with Condition No. 15(c) of the license.

License Nos. -2 and -7 allow for three-year leak tests
of certain Cs-137 sealed sources. AEC-591 forms were
issued as a result of the inspection of these two licenses.

→ cc: G. A. Blanc, CO:II

cc: License No. 47-260-4

" " 47-260-2



Not Reproduced
For Sale

A-179