

June 5, 2007

Brosz
Engineering, Inc.

3030 Airport Rd., Ste. A, Box 23
Pierre, SD 57501
Phone: (605)224-1123
Fax: (605)224-0659

US Nuclear Regulatory Commission
Washington, DC 20555
Attention Document Control Desk

Registered in North Dakota, South Dakota, and Montana

Docket No: 030-34296/07-01
License No: 40-27551-01

RE: Reply to a Notice of Violation

To Whom It May Concern:

I am writing in regards to the letter received on May 21, 2007.

There were two violations received after an inspection on April 25, 2007. We are taking corrective action on the two Level IV violations.

1. We have installed lead core sheet rock for the two inside walls of our storage room. Once we get all four nuclear gauges in the safe, we will perform our public dosage survey as described in Appendix I, Part 2 of the NUREG-1556, Vol 1, which is in response to item #1 violation.
2. We will conduct our annual radiation program at that time and keep them in a separate file. We will also send a copy to you for verification, which is in response to item #2 violation.
3. We have conducted annual radiation program content and implementation in the past, the reports must have been misplaced in the file.

If you have any questions, please contact me.

Sincerely,



Blake Barringer, RSO
Brosz Engineering

cc: file.office/document/nucviolat.doc
US Nuclear Regulatory Commission
Regional Administrator, Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-4005

FSME02
FSME