

Facilities Management

June 13, 2007

700 West Grace Street, Suite 2200
P.O. Box 842502
Richmond, Virginia 23284-2502

U. S. Nuclear Regulatory Commission, Region I
Division of Nuclear Materials Safety
Licensing Assistance Team
475 Allendale Road
King of Prussia, PA 19406

NMSBL

804 828-0769
FAX: 804 828-1288
TDD: 1-800-828-1120
www.vcu.edu/fmd/

Dear Sir or Madam:


03003297

RE: NRC Byproduct Materials License 45-00048-17
Request for Amendment

The University would like to request that its license be amended to remove Conditions 22.A. and 22.B. with regard to the disposal of licensed material by incineration. The Consumat incinerator (referenced in our license application dated September 29, 1999, and located at the licensed location) has never been used for the incineration of radioactive material. The old incinerator at this location used previously for incineration of small quantities of radioactive material has been out of commission since the mid-1980s. Our decommissioning survey records of this unit are available upon request.

As specified in Condition 22.B., we will notify the Chairman of the Board of Supervisors of Hanover County with regard to these actions once they have been approved. Should you have any questions or require any additional information, please contact Mary Beth Taormina in our Radiation Safety Section at (804) 828-7097. Thank you in advance for your assistance with this request.

Sincerely,



Brian J. Ohlinger, PE
Associate Vice President for Facilities Management

2007 JUN 18 PM 1:04
RECEIVED
REGION I

140690

NMSS/RGN1 MATERIALS-002

This is to acknowledge the receipt of your letter/application dated

6/13/2007, and to inform you that the initial processing which includes an administrative review has been performed.

ATTEND 45-00048-17
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 140690.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.