



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-4005

June 29, 2007

M. R. Blevins, Senior Vice President
and Principal Nuclear Officer
TXU Energy
ATTN: Regulatory Affairs
Comanche Peak Steam Electric Station
P.O. Box 1002
Glen Rose, TX 76043

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION, UNITS 1 AND 2 - NRC
EXAMINATION REPORT 05000445/2007301; 05000446/2007301

Dear Mr. Blevins:

On April 20, 2007, the U.S. Nuclear Regulatory Commission (NRC) completed an examination at Comanche Peak Steam Electric Station, Units 1 and 2. The enclosed report documents the examination findings, which were discussed on May 23, 2007, with Mr. Mark Kanavos, Plant Manager, and other members of your staff.

The examination included an evaluation of 5 applicants for reactor operator licenses, 3 applicants for instant senior operator licenses, and 4 applicants for upgrade senior operator licenses. The written and operating examinations were developed using NUREG-1021, "Operator Licensing Examination Standards for Power Reactors," Revision 9. It was determined that 11 of the 12 applicants satisfied the requirements of 10 CFR Part 55, and the appropriate licenses have been issued.

No findings of significance were identified during this examination.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Sincerely,

/RA/

Anthony T. Gody, Chief
Operations Branch
Division of Reactor Safety

TXU Energy

-2-

Dockets: 50-445; 50-446
Licenses: NPF-87; NPF-89

Enclosure:
NRC Examination Report 05000445/2007301;
05000446/2007301

cc w/ enclosure:
Fred W. Madden, Director
Regulatory Affairs
TXU Power
P.O. Box 1002
Glen Rose, TX 76043

George L. Edgar, Esq.
Morgan Lewis
1111 Pennsylvania Avenue, NW
Washington, DC 20004

Terry Parks, Chief Inspector
Texas Department of Licensing
and Regulation
Boiler Program
P.O. Box 12157
Austin, TX 78711

The Honorable Walter Maynard
Somervell County Judge
P.O. Box 851
Glen Rose, TX 76043

Richard A. Ratliff, Chief
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756-3189

Environmental and Natural
Resources Policy Director
Office of the Governor
P.O. Box 12428
Austin, TX 78711-3189

Brian Almon
Public Utility Commission
William B. Travis Building
P.O. Box 13326
Austin, TX 78711-3326

TXU Energy

-3-

Susan M. Jablonski
Office of Permitting, Remediation
and Registration
Texas Commission on
Environmental Quality
MC-122
P.O. Box 13087
Austin, TX 78711-3087

Lisa R. Hammond, Chief
Technological Hazards Branch
National Preparedness Division
FEMA Region VI
800 N. Loop 288
Denton, TX 76209

Electronic distribution by RIV:
 Regional Administrator (**BSM1**)
 DRP Director (**ATH**)
 DRS Director (**DDC**)
 DRS Deputy Director (**RJC1**)
 Senior Resident Inspector (**DBA**)
 Branch Chief, DRP/A (**CEJ1**)
 Senior Project Engineer, DRP/A (**TRF**)
 Team Leader, DRP/TSS (**CJP**)
 RITS Coordinator (**MSH3**)
 DRS STA (**DAP**)
 M. Kunowski, OEDO RIV Coordinator (**MAK3**)
ROPreports
 CP Site Secretary (**ESS**)

SUNSI Review Completed: Y No ADAMS: Yes No Initials: JFD
 Publicly Available Non-Publicly Available Sensitive Non-Sensitive

SOE/OB	SOE/OB	OE/OB	C:OB	C:PBA	C:OB
JFDrake/lmb	TFStetka	BTLarson	ATGody	CEJohnson	ATGody
/RA/	/RA/	/RA/	/RA/	/RA/	/RA/
6/13/07	6/18/07	6/18/07	2/24/07	6/25/07	6/28/07

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

EXAMINATION REPORT

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

Dockets: 50-445, 50-446
Licenses: NPF-87, NPF-89
Report: 05000445/2007301; 05000446/2007301
Licensee: TXU Generation Company LP
Facility: Comanche Peak Steam Electric Station, Units 1 and 2
Location: FM-56, Glen Rose, Texas
Dates: April 16 through May 23, 2007
Inspectors: Jim Drake, Chief Examiner, Operations Branch
Tom Stetka, Senior Operations Engineer
Brian Larson, Operations Engineer
Approved By: Anthony T. Gody, Chief
Operations Branch
Division of Reactor Safety

SUMMARY OF FINDINGS

ER 05000445/2007301, 05000446/2007301; 04/16-5/23/2007, Comanche Peak Steam Electric Station Units 1 and 2, Operator Licensing Initial Examination Report.

The NRC examiners evaluated the competency of 5 applicants for reactor operator licenses , 3 applicants for instant senior operator licenses, and 4 applicants for upgrade senior operator licenses at Comanche Peak Steam Electric Station, Units 1 and 2. The facility licensee developed the examinations using NUREG-1021, "Operator Licensing Examination Standards for Power Reactors," Revision 9. The written examination was administered by the facility on April 23, 2007. The NRC examiners administered the operating test April 16-20, 2007. It was determined that 11 of 12 applicants passed all portions of the examination.

A. NRC - Identified and Self- Revealing Findings

No findings of significance were identified.

B. Licensee - Identified Violations

None.

Report Details

4. OTHER ACTIVITIES (OA)

4OA5 OTHER ACTIVITIES (Initial License Examination)

.1 License Applications

a. Scope

The chief examiner reviewed all 12 preliminary applications and audited 2 of the license applications in accordance with NUREG 1021, "Operator Licensing Examination Standards for Power Reactors," Revision 9. Since the audit of the physical examination records identified comments and notes by the examining physician, which indicated potential disqualifying conditions in accordance with ANSI 3.4 1983 with no additional explanation for these conditions and no recommended restrictions on the license applications, the chief examiner performed a 100 percent audit of the physical examination records for the applicants. The audit found that two of the applicants had medical conditions that required restrictions on their license applications, although the preliminary applications had recommended no restrictions. Since this was identified by the chief examiner in the preliminary application review and corrected before the final applications were submitted, the issue is considered minor.

b. Findings

No findings of significance were identified.

.2 Operator Knowledge and Performance

a. Examination Scope

The NRC examination team administered various portions of the operating test to all 12 applicants on April 16 - 20, 2007. Most of the reactor operator and instant senior operator applicants participated in two or three dynamic simulator scenarios, a control room and facilities walkthrough test consisting of 10 or 11 system tasks, and an administrative test consisting of 4 administrative tasks for the reactor operator applicants and 5 administrative tasks for the instant senior operator applicants. The four applicants upgrading their reactor operator licenses to senior operator licenses participated in one scenario and took a control room and facilities walkthrough test consisting of 5 system tasks, and an administrative test consisting of 5 administrative tasks.

On April 23, 2007, the licensee proctored the administration of the written examinations to all 12 applicants. The licensee staff graded the written examinations, analyzed the results, and presented their analysis to the NRC on April 30, 2007

b. Findings

Written Test

All of the applicants passed the written examination. The average score for reactor operator applicants was 87 percent, and the average score for senior operator applicants was 82.9 percent for the senior operator portion of the examination and 87.4 percent for the combined written examination. The reactor operator applicant scores ranged from 81 to 93 percent, and the senior operator applicant scores ranged from 72 to 100 percent for the senior operator portion of the examination and 82 to 95 percent for the combined written examination.

NUREG 1021, Revision 9, Section ES-403, requires the licensee to analyze the validity of any written examination questions that were missed by half or more of the applicants. The licensee conducted this performance analysis for 11 questions. The licensee concluded that all questions were valid and conducted the necessary remediation with the applicants. After reviewing the licensee's analysis, the examiners agreed with the licensee's assessment.

Operating Test

After grading candidate performance, 11 of the 12 applicants passed all portions of the operating test. During the operating test, the examiners observed some generic weaknesses associated with: (1) the candidates demonstrated understanding of integrated plant operations; and (2) diagnosing malfunctions based upon plant instrumentation and indications.

The licensee agreed to develop remedial training for those candidates who passed the overall examination but demonstrated those weaknesses.

One administrative job performance measure was replaced during the examination because of typographical errors, which in conjunction with an ambiguous procedure rendered the job performance measure invalid. The licensee committed to revise the procedure.

.3 Initial Licensing Examination Development

a. Examination Scope

The licensee developed the examinations in accordance with NUREG-1021, Revision 9. Licensee facility training and operations staff involved in examination development were on a security agreement.

The facility licensee submitted the operating examination outlines on January 30, 2007. Examiners reviewed the submittal against the requirements of NUREG-1021, Revision 9, and forwarded comments to the licensee on February 5, 2007. The facility licensee submitted the draft operating examination package on February 12, 2007, and the draft written examination package on March 2, 2007. Examiners reviewed the draft submittals against the requirements of NUREG-1021, Revision 9, and provided

comments to the licensee for the draft operating examination on February 15, 2007, and comments for the draft written examination on March 20, 2007. The examiners conducted an onsite validation of the operating test and provided comments to the licensee during the week of February 26, 2007. The licensee satisfactorily completed comment resolution during the week of April 2, 2007.

b. Findings

Examiners approved the initial examination outline with minor comments and advised the licensee to proceed with the examination development.

The chief examiner determined that the operating and written examinations initially submitted by the licensee were within the range of acceptability expected for a proposed examination and were satisfactory after comment resolution.

No findings of significance were identified.

.4 Simulation Facility Performance

a. Scope

The examiners observed simulator performance with regard to plant fidelity and reliability during the examination validation and administration.

b. Findings

On April 16, 2007, the simulator had material problems that delayed the administration of the examination for several hours. The simulator was repaired and the examination schedule was rearranged to minimize the impact on the overall examination. This deficiency is documented in licensee Condition Report SMF-2007-001356-00. No other simulator deficiencies were noted during validation and no findings of significance were identified.

.5 Examination Security

a. Scope

The examiners reviewed examination security both during the onsite preparation and examination administration week with respect to NUREG-1021 requirements. Written plans for simulator security and applicant control were reviewed and discussed with licensee personnel.

b. Findings

No findings of significance were identified.

4OA6 Meetings, including Exit

Exit Meeting Summary

On April 20, 2007, the examination team presented a debrief to Mr. Steve Sewell, Operations Manager, and other members of the licensee's management staff at the conclusion of the operating test. The licensee acknowledged the findings presented. A subsequent telecom exit was conducted with Mr. Mark Kanavos, Plant Manager, and other members of his staff on May 23, 2007. The findings as detailed in this report and applicant performance during the examination were discussed.

The licensee did not identify as proprietary any information or materials used during the examination.

ATTACHMENT: SUPPLEMENTAL INFORMATION

SUPPLEMENTAL INFORMATION

KEY POINTS OF CONTACT

Licensee Personnel

Mark Kanavos, Plant Manager
Steven Sewell, Training Manager
Gary Caspersen, Operations Training Manager
Garry Struble, Operations Training Supervisor
Rob Slough, Regulatory Affairs

NRC Personnel

Don Allen, Senior Resident Inspector
Alfred Sanchez, Resident Inspector