

Mark B. Bezilla  
Vice President - Nuclear419-321-7676  
Fax: 419-321-7582

Docket Number 50-346

License Number NPF-3

Serial Number 3356

July 31, 2007

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555-0001Subject: Correction of Information Provided in Previous Submittals Regarding Number of  
Leaking Control Rod Drive Mechanism (CRDM) Flanges


Ladies and Gentlemen:

The purpose of this letter is to correct a minor discrepancy that was identified with previous submittals related to the Davis-Besse Nuclear Power Station (DBNPS). By letters dated April 18, 2002 (Serial Number 1-1270), dated August 21, 2002 (Serial Number 1-1286), and dated September 23, 2002 (Serial Number 1-1289) the DBNPS submitted to the NRC root cause analysis reports related to the degradation of the DBNPS reactor pressure vessel head discovered during the thirteenth Refueling Outage (13RFO). The root cause analysis reports provide a historical timeline of CRDM flange leaks. The timelines of each of the root cause analysis reports textually stated (Serial Number 1-1270 page 27, Serial Number 1-1286 page 21, Serial Number 1-1289 page 31) in 1991 (7RFO) that 21 CRDM flanges were identified as leaking, while Serial Number 1-1270 and Serial Number 1-1289 Figure 28 depicted 22 leaking CRDM flanges discovered in 7RFO. The correct number of leaking CRDM flanges discovered in 1991 (7RFO) is 22. This discrepancy was discovered during the review of documents while preparing DBNPS letter Serial Number 3350, "Response to Demand for Information," dated June 13, 2007. This discrepancy in the original submittals has been documented and addressed through the DBNPS Corrective Action Program, and has been determined to have no safety significance.

The FirstEnergy Nuclear Operating Company (FENOC) does not believe that the minor discrepancy being corrected by this letter constitutes information that is inaccurate or incomplete in any material respect.

If you have any questions or require additional information, please contact Mr. Raymond A. Hrubby, Jr., Manager – Regulatory Compliance, at (419) 321-8000.

Very truly yours,



Mark B. Bezilla, Vice President - Nuclear

TSC

A 001

MRK

Docket Number 50-346  
License Number NPF-3  
Serial Number 3356  
Page 2 of 2

Attachment 1: Commitment List

cc: Regional Administrator, NRC Region III  
DB-1 NRC/NRR Project Manager  
DB-1 Senior NRC Resident Inspector  
Utility Radiological Safety Board

Docket Number 50-346  
License Number NPF-3  
Serial Number 3356  
Attachment 1  
Page 1 of 1

**COMMITMENT LIST**

The following list identifies those actions committed to by the Davis-Besse Nuclear Power Station in this document. Any other actions discussed in the submittal represent intended or planned actions by Davis-Besse. They are described only for information and are not regulatory commitments. Please notify the Manager – Regulatory Compliance (419) 321-8000 at Davis-Besse of any questions regarding this document or associated regulatory commitments.

**COMMITMENTS**

**DUE DATE**

None

N/A