



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
611 RYAN PLAZA DRIVE, SUITE 400  
ARLINGTON, TEXAS 76011-4005

August 6, 2007

Taylor Engineering, Inc.  
ATTN: Randy P. Budano  
Radiation Safety Officer  
106 West Mission Avenue  
Spokane, Washington 99201

SUBJECT: NRC INSPECTION REPORT 030-37404/2007-001 (FORM 591M)

Dear Mr. Budano:

This letter and the enclosed NRC Form 591M refer to the inspection conducted, June 20, 2007, at your field office in Athol, Idaho. In addition, inspection followup calls were conducted with you on July 12 and 18, 2007, as well as the receipt of requested information contained in your facsimiles dated June 20, and July 12, 2007. This inspection was an examination of activities conducted under the authority of Byproduct Materials License 46-29250-01 as they relate to safety and compliance with the Commission's rules and regulations and with the conditions of the license. A final exit briefing was conducted telephonically with you on July 18, 2007.

Within the scope of this inspection, no violations were identified; therefore, no response to this letter or the enclosed NRC Form 591M is required.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

Should you have any questions concerning this inspection, please contact me at 817-860-8187.

Sincerely,

*/RA/*

Richard Leonardi, Senior Health Physicist  
Nuclear Materials Inspection Branch

Docket No.: 030-37404  
License No.: 46-29250-01

Enclosure: As stated  
cc w/enclosure:  
Idaho Radiation Control Program Director  
Washington Radiation Control Program Director

bcc w/enclosure (via ADAMS e-mail distribution):

LDWert

CLCain

VHCampbell

JEWhitten

RALeonardi

RITS Coordinator

NMIB

RIV Materials Docket File - 5<sup>th</sup> floor

SUNSI Review Completed: RAL ADAMS:  Yes  No Initials: RAL

Publicly Available  Non-Publicly Available  Sensitive  Non-Sensitive

DOC. NAME: S:\DNMS\!Nmib\reports in concurrence\Taylor Engineering 07-01.wpd final r:\\_dnms

RIV:DNMS:NMIB	C:NMIB
RALeonardi	VHCampbell
<b>/RA/</b>	<b>/RA CLCain for/</b>
08/06/2007	08/06/2007

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

### SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

**Taylor Engineering, Inc.  
106 West Mission Avenue  
Spokane, Washington 99201**

2. NRC/REGIONAL OFFICE

**USNRC Region IV  
611 Ryan Plaza Drive, Suite 400  
Arlington, Texas 76011-4005**

REPORT NUMBER(S) **2007-001**

3. DOCKET NUMBER(S)

**030-37404**

4. LICENSEE NUMBER(S)

**46-29250-01**

5. DATE(S) OF INSPECTION

**June 20 through July 18, 2007**

#### LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

\_\_\_\_\_ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

#### Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Richard Leonardi	/RA/	08/06/2007