

## SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

## 1. LICENSEE/LOCATION INSPECTED:

Richard E. Pierson Construction Company, Inc.  
P. O. Box 430  
Woodstown, New Jersey 08098-0430

## 2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission  
Region I, 475 Allendale Road  
King of Prussia, Pennsylvania 19406-1415

REPORT Nos 2007-001

## 3. DOCKET NUMBER(S)

03034072

## 4. LICENSE NUMBER(S)

29-30279-01

## 5. DATE(S) OF INSPECTION

July 25, 2007

## LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☒ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

☐ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):



- ☒ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 30.41 requires that the licensee before transferring byproduct material to a specific licensee of the Commission shall verify that the transferee's license authorizes the receipt of the type, form, and quantity of byproduct material to be transferred. The licensee did not use one of the acceptable methods in 10 CFR 30.41 for verifying the transferee is authorized to receive the byproduct material. Specifically the licensee transferred a Trawler portable gauge to New Jersey DOT.

The licensee will obtain a copy of the transferee's license.

## Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	ROB BACCALA		7/25/07
NRC INSPECTOR	Judith A. Joustra		7/25/07

