

ENCLOSURE

NOTICE OF VIOLATION

Tennessee Valley Authority  
Watts Bar 1 and 2

Docket Nos. 50-390 and 50-391  
License Nos. CPPR-91 and CPPR-92

The following violation was identified during an inspection conducted on November 21 - December 20, 1985. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50, Appendix B, Criterion V as implemented by TVA's QA Topical Report TVA-TR-75-1A, Rev. 8, paragraph 17.1.5 requires that activities affecting quality shall be prescribed by procedures of a type appropriate to the circumstances.

Contrary to the above, weld inspection activities were not adequately prescribed in that welding inspection procedure, QCP-4.13, did not require that welding QC inspectors verify a welder's qualifications meet ASME Sec. III requirements.

This is a Severity Level IV violation (Supplement II).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: JAN 17 1986

8601290297 860117  
PDR ADOCK 05000390  
G PDR