



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II

101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

OCT 09 1980

In Reply Refer To:
RII:JAM
50-390/80-23
50-391/80-17

Tennessee Valley Authority
ATTN: H. G. Parris
Manager of Power
500A Chestnut Street Tower II
Chattanooga, TN 37401

Gentlemen:

This refers to the inspection conducted by J. A. McDonald of this office on July 1 through 31, 1980 of activities authorized by NRC Construction Permit Nos. CPPR-91 and CPPR-92 for the Watts Bar Nuclear Plant facility, and to the discussion of our findings held with C. C. Mason and J. E. Wilkins at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

We have examined actions you have taken with regard to previously identified enforcement matters. These are discussed in the enclosed inspection report.

One new unresolved item resulted from this inspection and is discussed in the enclosed report. This item will be examined during subsequent inspections.

During the inspection, it was found that certain activities under your license appear to be in noncompliance with NRC requirements. These items and references to pertinent requirements are listed in the Notice of Violation enclosed herewith as Appendix A. This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within 20 days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective steps which have been taken by you and the results achieved; (2) corrective steps which will be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

In addition to the need for corrective action regarding these specific items of noncompliance, we are concerned about the implementation of your management control systems that permitted their occurrence. Consequently, the findings in this report will be discussed during the management meeting, tentatively scheduled for October, referenced in the enclosure to our letter of July 28, 1980.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is

8105210319

Q

001 0 1980
MAIL A 000

necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,



R. C. Lewis, Acting Chief
Reactor Operations and Nuclear
Support Branch

Enclosures:

1. Appendix A, Notice of Violation
2. Inspection Report Nos. 50-390/80-23
and 50-391/80-17

cc w/encl:

- C. C. Mason, Acting Plant
Superintendent
- J. E. Wilkins, Project Manager
- J. F. Cox, Supervisor, Nuclear
Licensing Section
- D. P. Ormsby, Project Engineer
- H. N. Culver, Chief, Nuclear
Safety Review Staff