

APPENDIX A  
NOTICE OF VIOLATION

Tennessee Valley Authority  
Watts Bar 1

Docket No. 50-390  
License No. CPPR-91

As a result of the inspection conducted on October 26-28, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified.

10 CFR 50, Appendix B, Criterion V as implemented by Watts Bar FSAR Section 17, paragraph 17.1A.5 requires activities affecting quality be accomplished in accordance with instructions, procedures or drawings. Watts Bar QCP 4.23 R2 paragraph 6.6.4 requires that temporary or permanent removal of a documented or partially documented support shall be authorized by a "Support Removal - Reinstallation Sheet" issued by the Hanger Engineering Unit.

Contrary to the above, on October 27, 1981, activities affecting quality were not being accomplished in accordance with documented procedures in that the inspection of three piping hangers or restraints revealed partial disassembly or modification had been performed without the procedural authorization form.

This is a Severity Level V Violation (Supplement II.E). This applies to Unit 1 only.

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

The responses directed by this Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Date: NOV 18 1981

8201270163 820108  
PDR ADDCK 05000390  
PDR