ENGINEERING SERVICES INC ATTINI TONY Stemen

001



32232 Schoolcraft Road, Suite C-3 - Livonia, Michigan 48150

R.K. ENGINEERING A Division of Engineering Services

Telephone: (734) 525-7330 - Fax: (734) 525-7255 e mail: esi786@sbcglobal.net - website: www.esi-engr.com

SEPTEMBER 06, 2007

Ms. Toy Siemen Material Licensing Branch United States Nuclear Regulatory Commission Region III

Re: License No. 21-26742-01

Dear Ms Toy Siemen,

Thank you for amending our Material License No. 21-26742-01, with regard to the address correction.

- We are writing this letter to request you to release the former storage area located at 32300 Schoolcraft roads. We are enclosed the following information for your review in this regards.
- History of all Radionuclides Stored in former Storage Area: Engineering Services, Inc (ESI) occupied the 32232 Schoolcraft Road between June 2007 and August 2007. The gauge consists of a sealed source of Cesium -137 and Americium-241. During this period of gauge storage, Inventories, leak tests were performed to monitor the gauge. No evidence of any leakage was apparent at 32300 Schoolcraft
- Copy of the Leak Test Report performed at former Storage Area.; ESI performed . leak test on April 24,2007 at the former storage area. Result indicated less than 0.005 muCi.

Road location. The inspection did not reveal any violation at this location.

If you have any questions, please do not hesitate to call.

Miraj Mehta

Coll ----

Field Engineer

Very truly yours,

ENGINEERING SERVICES, INC. By:

H- Lev

Hakim Shakir, P.E. Principal



C: Documents and Settings/ESI Miraj/My: Documents/ESI Miraj Year 02.03 04/Miraj/2007 Inspection Report/T.H.Marsh/steel Inspection.wpd T.H.Marsh March 08 .wpd